

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 043010

PRIMARY CORNER DESCRIPTION NE Cor. Yocum DLC #43

Alias 044020 Description NW Cor. Preston DLC #44  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original DLC survey by Bowman and Burnett under Contract date  
Sept. 24, 1855

-----  
(DLC #43 notes call):  
Set a post marked as per instructions, from which  
A W.Oak 14" dia., bears S.65°W., 653 lks.

-----  
(DLC #44 notes call):  
A post marked as per instructions from which  
A Yellow pine 4" dia., bears S.72½°E., 395 lks.

John H. Markham, Jr. - For: E.J. Puddicombe - April 1949 -  
C.S. File 40/189

-----  
Set from NE Cor. found.  
Set 1" I.P. 40" long, from which  
5" Fir bears S.66°W., 8.5 ft. mkd. CL 44 2880 BT.  
19" Fir bears S.78°E., 33.5 ft. mkd. CL 44 2880 BT.

Doug. County Surveyors Office - James Byron, Deputy - Mike  
Darby; Jim Halterman - Oct. 1963 - C.S. File 53/26-21

-----  
Found - 1" I.P. at corner and at N-S fence line.  
24" R.Fir S.78°E., 33.5 ft. shows good scar.  
SW BT down.  
New BT - 10" R.Fir bears S.32°W., 14.7 ft. scribed NW DLC 44  
CS BT.

Fd. I.P. as per record, R. Brown, May 1993, M 112-76 ABC  
Fd. Ok by R.Brown, 2/97, M 124-41.

DCSO-GIS Corner visitation - 12/15/2004 - Typed: 2/2/2011 -  
C.S. File 67/33-1

-----  
Monument - 1" IP  
Comment - (needs) rehab

Fd. ok by D. Edwards, 10/2005 - M148-61