

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 044040

PRIMARY CORNER DESCRIPTION S SE Cor. Preston DLC #44

Alias <u>046050</u>	Description <u>SW Cor. N Briggs DLC #46</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original DLC survey by Bowman and Burnett under Contract date Sept. 24, 1855

-----  
(Notes for DLC #44)

Set a post marked, from which

A B.Oak 18" dia., bears N.42½°W., 42 lks.

-----  
(Notes for DLC #46)

A post marked as per instructions, from which

A W.Oak 24" dia., bears N.50°E., 100 lks.

Raymond Brown, L.S. #2391 - For: Roy and Donys Nelson - May 1993 - M 112- 76 ABC

-----  
At point for SE Cor. DLC #44 and SW Cor. of DLC #46.

Set 2" x 36" I.P. with 3" brass cap attached, from original bearing trees, mkd. "P.L.S. 2391, Sly SE Cor.DLC 44, SW Cor. DLC 46, 1993".

From which

Orig. 24" Oak stump bears N.39°00'W., 27.72 ft. found scribe "BT", recorded as per GLO, 18" B.Oak bears N.42°30'W., 27.72 ft.

30" Oak stump bears N.50°10'E., 66.0 ft. found scribing on pulled blaze "T30 R5 46" recorded as per GLO, 24" W.Oak bears N.50°E., 66.0 ft.

New BTs -6" Oak, N.36°41'W., 24.9 ft. mkd. "SE DLC 44".

7" Madrona N.47°38'E., 15.6 ft. mkd. SW DLC 46 BT.

6" Madrona S.21°23'E., 17.0 ft. mkd. DLC 44/46 BT.

8" Madrona S.48°03'W., 23.6 ft. mkd. DLC 44/46 BT.

DCSO-GIS Corner visitation - 1/13/2005 - Typed: 2/2/2011 - C.S. File 67/33-1

-----  
Monument - BC/IP - 3" BC

Comment - OK

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - 10/10/2012 - C.S. File 67/36-43

-----  
Reported as not found.

Monument destroyed; falls in rock quarry excavation.

All accessories destroyed by quarry exaction.

Note: Mon location falls in pit tier access rd of active rock quarry.