

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 048040

PRIMARY CORNER DESCRIPTION W. Int. SW Cor. J. Gazely DLC #48

Alias <u>050010</u>	Description <u>N. NE Cor. Colviy DLC #50</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original DLC survey by Bowman and Burnett under Contract date Sept. 24, 1855

-----  
A Stake, marked, from which  
A Fir 24" dia., bears S.85°E., 87 lks.

E. Summers - For: Bollenbaughs' - Apr 2, 1920 - Vol. 3 Pg. 68

-----  
Reset from old field notes. Set stone, from which new bearing trees are as follows;  
Maple 20" dia., bears S.22°30'W., 209 lks.  
B.Oak 36" dia., bears N.56°30'W., 116 lks.

Doug. County Surveyors Office - James W. Byron, Deputy - Milo Godfrey; C. Putnam - For: Doug. Co. Parks Dept. - March 1, 1961 - C.S. File 52/72; RM 2-10

-----  
Set brass cap mkd: N.E. Cor. DLC 50 T30S R5W.  
Found - now 30" Maple, shows good scribing "CS DLC 50" bears S.22½°W., 137.9 ft.  
New BTs -20" Cedar bears S.63°W., 71.0 ft.scribed NE DLC 50 CS BT.  
7" B.Oak bears N.56°W., 81.5 ft. scribed NE DLC 50 CS BT.

Brass cap missing, per M 54-17, Aug. 1974

Raymond Brown, L.S. #2391 - For: Lois M. Clough - April 1990 - M 101-78

-----  
Set - 2" x 36" Iron pipe with brass cap attached 12" below surface mkd. "L.S. 2391, T30S R5W NE Cor. DLC 50 1990"

New Accessories:  
12" Maple bears N.51°40'E., 197.7 ft. mkd. "NE DLC 50 BT."  
12" Cedar bears N.12°30'W., 181.9 ft. mkd. "NE DLC 50 BT."  
7" D.Fir bears N.40°W., 114.7 ft. mkd. "NE DLC 50 BT".  
Power Pole (plate No. PPL 30-05 217500) bears S.74°37'E., 5.3 ft. to center.

Old Accessories:  
3/4" Iron Rod bears S.87°23'W., 53.7 ft. (RM 2-10)  
3/4" Iron Rod bears S.2°37'E., 427.2 ft. (RM 2-10)  
20" Cedar now 34" S.62°W., 71.0 ft. with good scar.

(Cont. Next Page)

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 048040

PRIMARY CORNER DESCRIPTION W. Int. SW Cor. DLC #48

Alias 050010 Description N. NE Cor. DLC #50

Alias \_\_\_\_\_ Description \_\_\_\_\_

Alias \_\_\_\_\_ Description \_\_\_\_\_

Alias \_\_\_\_\_ Description \_\_\_\_\_

7" B.Oak, not able to locate.  
30" Maple is dead and has fallen down.  
This corner was reset from accessories as per RM 2-10 and  
C.S. 52/72.

Douglas Co. Surveyors Office - Stephen Flauser - Mike Koch -  
Sept. 17, 2012, filed 12/5/2018 - C.S. File 67/45-12

-----  
Condition report  
BC below ground as described  
NW 7" Fir is fallen and rotted.  
NE 12" maple is an ash.  
All other accessories are fd as described.  
We re-tag and flag as needed  
Dec. 15½°E