

PRIMARY CORNER DESCRIPTION Int SE Cor Clark DLC #51

Alias	Description

<p>Original DLC survey by Bowman and Burnett under Contract date Sept. 24, 1855</p> <p>-----</p> <p>Set a post marked, from which A Laurel 9" dia., bears N.40°W., 90 lks.</p>
<p>George J. Wenderoth, Deputy Co. Surveyor - Frank Loso; Charles Leiser - May 1949 - C.S. File 40/270</p> <p>-----</p> <p>Found - Old BT, 16" madrone N.40°W., 59.4 ft., dead and rotten.</p> <p>Drive 1½" Iron pipe for corner. Scribe - 8" W.Oak S.50°25'E., 27.9 ft. 10" W.Oak S.30°W., 36.2 ft.</p>
<p>Fd. I.P., Oct. 1985, J. Markham, M 99-58 Fd. OK, July 1986, K. DeGroot, M 102-27 Fd. I.P., April 1993, G. Baughman, Partition 1993-0028 Fd. OK, July 1993, G. Baughman, M 117 - 38 FD. OK, MAR 1995, K. DEGROOT, 1995-0044 Fd. Ok April 2005, R. Brown, 2005-0063A&amp;B</p>
<p>Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Oct. 25, 2012 - C.S. File 67/36-32</p> <p>-----</p> <p>Found - 1½" ID iron pipe firmly set and leaning very slightly SW'erly protrudes 3" above ground. 1949 Evidence of the one OBT fd: A fallen and mostly rotted away madrone the root-hole of which bears N.40°W., 59.4 ft. (as per rec)</p> <p>An 8" W.Oak, now a 9" dia., W.Oak with a fully healed double blaze; bears S.52½°E., 27.9 ft. (Rec. S.50½°E., 27.9 ft.) 1949</p> <p>A 10" W.Oak, now an 11" dia., fallen and out of position Oak (no blaze evident probably on underside of trunk) the root-hole of which bears S.30°W., 36.2 ft. (as per rec.) 1949</p> <p>New - A 6" dia., W.Oak, scribed "X" "CSBT" on a high-low double blaze; bears N.79¼°E., 10.0 ft. A e" dia., iron rod with a PLS Baughman plastic cap set protruding 4" above ground; bears South 7.5 ft. (as per DCSO file part. 1993-0030) An 8" dia., Ponderosa Pine scribed "INT L DLC 51 CS" "BT" on a double blaze; bears S.68°W., 18.0 ft.</p> <p>Note - Corner is on steep NW slope in mixed forest of Oak, madrone, Pine &amp; Fir. Compass decl. 15½°E.</p>