

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 055040

PRIMARY CORNER DESCRIPTION Int. SW Cor. T Smith DLC #55

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Original DLC survey by Bowman and Burnett under Contract date Sept. 24, 1855</p> <p>-----</p> <p>Set a post marked, from which A B.Oak 28" dia., bears S.67½°E., 56 lks. dist.</p>
<p>J.H. Markham, Jr. - D.L. Combs, owner - March 1953 C.S. File 41/140-2</p> <p>-----</p> <p>Determined by O.B.T., a stump hole bears S.67½°E., 37.0 ft. At corner, Set 3/4" x 16" Iron Bolt. 36" B.Oak bears N.40°E., 45.4 ft. mkd. DLC XXX BT Fence bears S. and W. from corner. Sec. cor. bears East, 1335.0 ft.</p>
<p>Douglas Co. Surveyors Office - Stephen J. Flaue - John Pike - 12/13/2004 - C.S. File 67/6-33</p> <p>-----</p> <p>Found - Iron bolt flush with top of ground. Bolt measures 1¼" across top fd. near concrete fence corner post. No accessories fd - No new monument set.</p> <p>New - NW corner of house bears N.17°E., 34.8 ft. NW corner of garage bears S.42°E., 16.3 ft. 27" DBH W.Oak bears S.84°W., 13.0 ft. double blazed &amp; scribed "INT SW DLC 55 CS BT" 1/2" iron rod at SE cor. parcel 2 of Land Partition filed as M78-71 bears N.7°W., 170.1 ft. (rounded off rec. per M78-71)</p> <p>Note - Corner lies near house in fence corner with dilapidated fences extending West &amp; South. Decl. 17¼°E.</p>
<p>Fd. 3/4" iron bolt per rec. - 2/2024 - B Heichel - M185-2</p>
<p> </p>