

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 062010

PRIMARY CORNER DESCRIPTION NE Cor. Preston DLC #62

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Original DLC survey by Bowman and Burnett, under Contract date Sept. 1855</p> <p>-----</p> <p>Set a post marked, from which</p> <p> A B.Oak 20" dia., bears S.30°W., 70 lks.</p> <p> A B.Oak 15" dia., bears East, 50 lks.</p>
<p>John Markham, Jr. - For: E.E. Pickett - Wit: Vaughn & Pickett Dec. 3, 1949 - C.S. File 40/234</p> <p>-----</p> <p>Determined from remains of O.B.T., a stump hole bearing S.35°W., 60 lks. (Rec. S.30°W., 70 lks.)</p> <p>At corner point, found ½" I.P. and mound of rocks, from which</p> <p> 11" W.Oak bears S.7°W., 35.0 ft. mkd. CL 62 2880 BT.</p> <p> 19" W.Oak bears N.6°E., 141.0 ft. mkd. CL 62 2880 BT.</p>
<p>Douglas County Surveyors Office - Randall Smith & Stephen Flause - Mar. 5, 1997 - C.S. 64/71-14</p> <p>-----</p> <p>Mon. Fd.- ½" I.R. set in a ½" I.D. iron pipe. Top of I.R. 9" below road surface, I.P. 5" below top of I.R. (source of I.P. unknown I.R. set by Fred Hooper property owner).</p> <p>Bt's Fd.- 11" now 26" dia. W.Oak with a fully healed single blaze, bears S.9½°W., 35.6'.</p> <p> 19" now 36" dia. W.Oak with a fully healed double blaze, bears N.6°E., 141'.</p> <p> 5/8" I.R. is found 4" below road surface, bears S.43°W., 5.64' (rec. S.47°43'W., 5.64' M84-45).</p> <p> 1¼" iron rod found 6" below road surface, bears N.43°E., 13.07' (rec. 47°43'E., 13.07 per M84-45) set by Fred Hooper property owner approx. 25 yrs. ago.</p> <p>Talked with property owner in area Fred Hooper, said he had set ½" I.R. inside ½" I.P. at corner and set 1¼" I.R. to reference corner position.</p>
<p>FD. OK - L. Maddux - Sept. 20, 1997 - 1997-0111</p> <p>Found OK by D. Beedle, Jan. 2001 - M136-44</p> <p>Fd. Ok by R. Brown, 9/2014 - M166-14</p> <p>Fd. ½" IR inside ½" IP, by R.Brown, 3/2021 M179-33</p>
<p> </p>