

PRIMARY CORNER DESCRIPTION S.W. 1/16 Cor. Sec. 32

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Doug. County Surveyors Office - Gary Langlitz; Ed Monrean; P. Earle; Karen Reed; Vicki Woodral; F. Silagy - July 10, 1979 - C.S. File 61/3; RM 3-26

-----  
At the intersection of lines between properly proportioned corners as determined by survey:

We Set a 1" x 36" I.P. 30" into the ground attached brass cap is stamped: "Douglas County Surveyor" T30S R5W SW 1/16 S32 1979"

New BTs -8" D.Fir scribed "SW 1/16 S32 CS BT" on a double blaze bears N.86½°W., 51.9 ft.

8" D.Fir scribed "SW 1/16 S32 CS BT" on a double blaze bears S.60°E., 23.9 ft. to the center of the base. The center of the tree at the "BT" blaze bears S.86½°E., 21.3 ft.

No other suitable trees available in the area to reference.

-----  
Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 1/9/2007 - C.S. File 67/21-15 & M146-53

Found - 2½" dia., DCSO brass cap (properly mkd) projects 8" above ground.

8" now 21" dia. D.Fir, now pistol butt, fully healed double blaze, bears S.86½°E., 21.3 ft. to center of tree at lower healed blaze. (Agrees w/rec.)

8" now 23" dia., D.Fir, fully healed double blaze, bears N.86½°W., 51.9 ft. (agrees w/rec.)

New - 2½ dia., Brass cap on 1¼" O.D.x30" long iron pipe projects 8" above ground. BC mkd:

DOUGLAS CO SURVEYORS OFFICE 2007

T 30 S R 5 W

SW 1/16

S 32

**1979 brass cap is cut off remaining 1¼" O.D. iron pipe projects 6" above ground & now becomes an accessory to new position. Bearing tree tags are removed from trees witnessing the 1979 position.**

8" dia., D.Fir, double blazed & scribed "SW 1/16 S32 CS BT" bears S.74°W., 15.3 ft.

10" dia., double blazed & scribed "SW 1/16 S32 CS BT" bears N.2½°E., 15.7 ft.

1¼" O.D. iron pipe, flush w/ground, bears N.75°39'50"W., 217.32 ft.

Note - Corner lies on steep NW'ly facing slope approx. 7 ft. east of dilapidated N-S fence line.

Compass decl. 16¼°E