

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. Section 32

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

John Howard Markham, Jr. Eng. #2880 - Wit: R.E. Procter - Nov. 19, 1952 - C.S. File 41/82-2

At center of sec. 32, Set 3/4" x 14" Iron pipe, from which
A W.Oak 12" dia., bears S.70°W., 37.0 ft. mkd. ¼S CC BT.
A W.Oak 15" dia., bears N.50°W., 56.0 ft. mkd. ¼S CC BT.
Corner lies on East edge of private road. Centerline of Co. Rd. bears North, 680 ft.
The E, N, and W. edge of the Sec. was chained around and a traverse through the middle. The center was calculated.

Doug. County Surveyors Office - James W. Byron, Deputy - Ray Irving; John Fee - For: Douglas Co. Land Dept. - Aug/Nov. 1954 - C.S. File 46/64

Set 3/4" Iron rod at intersection of true section lines, Sec. 32. Blazed and scribed:
10" W.Oak N.31½°E., 89.7 ft. mkd. C ¼ S32 CS BT.
10" W.Oak S.65½°E., 53.3 ft. mkd. C ¼ S32 CS BT.

Doug. County Surveyors Office - Gary L. Langlitz; Larry E. Monrean; Stephen J. Flause; Frank C. Silagy - August 8, 1979 - C.S. File 61/3; RM 3-26

Found - A 3/4" I.Rod flush with ground, set by Byron in 1954
From which
10" W.Oak now 16" bears N.31½°E., 89.7 ft. Oak is a double tree with double blaze partial scribing visible.
Markham's Corner set in 1952 bears approx. S.88°E., 93.4 ft. from Byron's Iron rod. Markham's monument not found. One BT, a 15" dia. W.Oak now 18" bears N.46°W., at center of base (tree being a double tree) 55.6 ft. (Rec. N.50°W., 56.0 ft.) with well healed double blaze on southerly trunk.

These corners were surveyed in, using ¼ corners as determined by our 1979 survey of this area, therefore we re-position this corner. We leave old monument and accessories intact. Set a 1" x 36" I.P. with brass cap stamped: "Douglas County Surveyor" T30S R5W C ¼ S32 1979. Byron's I.Rod bears S.73°E., 97.7 ft.
New BTs -15" Pine scribed "C ¼ S32 CS BT" in a double blaze bears N.58°E., 25.6 ft.
10" D.Fir scribed "C ¼ S32 CS BT" in a double blaze, bears S.5°E., 62.5 ft.

continued next page

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 240140

PRIMARY CORNER DESCRIPTION Center 1/4 Cor Section 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Found OK by R. Brown, Jan. 2002 - M139-48
Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 1/31/2007 - C.S. File 67/21-6 & M146-53 ----- Found - 2½" dia., brass cap, properly mkd flush w/ground. 15" now 27" dia., Pine, fully healed double blaze. Found as per rec. 10" now 12" dia., D.Fir snag, 6 ft. tall, fully healed double blaze. Found as per rec. Set - 2½" dia., brass cap, on 1¼" O.D. IP 30" long. BC projects 6" above ground. <u>Markings are removed from 1979 BC which now becomes an accessory for 2007 position. BTs tags are removed from Pine & D.Fir snag.</u> 7" dia., Ponderosa Pine double blazed & scribed "C¼ S32 CS BT" bears S.39¾°W., 12.2 ft. 2½" dia., BC marks obliterated, flush w/ground bears N.74°49'08"W., 95.53 ft. ¾" dia., iron rod, top is bent southerly & flush w/ground bears S.23°40'25"E., 3.42 ft. Note - Corner lies approx. 77 ft. West from center of Jordan Crk. Rd. on nearly level ground. Compass decl. 16¼°E.
Fd. Ok by R. Brown, Aug. 2009 - M157-16
Fd. both C¼ corners 6/2013 - By D. Beedle - M165-29
Ron Quimby - For: C & D Lumber - 10/2018 - M175-1 ----- FOUND - 2½" Brass cap per M146-53 11" P.Pine S.39°W., 12.2' w/healed blaze [S.39¾°W.] 2½" Brass cap N.75°W., 95.53' [74°49'08"W] ¾" Iron rod S.23°E., 3.42' [S23'40'25W] New BT - 4" Pine S.3°W., 12.6' scribed "X"