

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 17 Page 7150)

Set ¼ sec. post, from which
A W.oak 15" dia., bears N.42°E., 50 lks.
A B.Oak 8" dia., bears N.25°W., 30 lks.

W. F. Briggs, For: Ed Weaver - June 27, 1885 - Vol. 1 Pg. 62 and "old" Cor. Bk. Page 183

Set Post. W.Oak 15" dia., bears N.42°E., 50 lks.
B.Oak 8" dia., bears N.25°W., 30 lks.

John H. Markham, Jr. - Wit: P.F. Willhoit - April 25, 1955 - C.S. File 41/387

Determined by O.B.T.:
23" W.Oak bears N.44°E., 33.0 ft.
Found a 1½" Iron pipe at corner point, from which
40" B.Oak bears N.25°E., 65.0 ft. mkd. ¼ S 16 BT.
23" B.Oak bears N.87°W., 33.0 ft. mkd. ¼ S S17 BT.
22" B.Oak bears S.42°E., 69.5 ft. mkd. ¼ S16 BT.

Doug. County Surveyors Office - James Byron, Deputy - Mike Darby - Sept. Oct. 1963 - C.S. File 53/26-8

Found - Snag of orig. NE BT.
Also found Markham's BTs:
40" B.Oak should be N.20°E., 65.0 ft., not N.25°E.
23" B.Oak should be S.87°W., not N.87°W.
Did not find 1½" I.P. set at corner. (See C.S. 49/38)
Set Brass cap at cor. mkd: County Surveyor's Office, 1963
¼ S17|S16 T30S R5W
Fence corner runs South and West.

Fd. 1963 brass cap and Markham's BTs. by BLM resurvey by Lynn Roseberry & James Jelley, under Group #662 -Surveyed Oct. 1967/June 1969 (DCSO records, Vol. 38 Page 15548)

Fd. Ok by R Brown, 3/2002 - M 139-76

DCSO-GIS Corner visitation - 1/3/2005 - Typed: 2/8/2011 - C.S. File 67/33-1

Monument - 1¼" IP/BC Comment - (needs) rehab

Fd. Ok by K DeGroot, 7/2006 - M146-42