

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>Original - Oscar F. Thiel, under Contract #658 dated May 21, 1896 (DCSO records, Vol. 17 Pages 7179-80)</p> <p>-----</p> <p>Set a basalt stone 12 x 10 x 7 ins., 8" in the ground for ¼ sec. cor. mkd. ¼ on N. face; from which</p> <p> A Laurel 7" dia., bears S.41°E., 12 lks. dist.</p> <p> A Fir 8" dia., bears N.35°W., 10 lks. dist.</p>
<p>Doug. County Surveyors Office - James Byron, Deputy - Milo Godfrey; S.A. Bilow - March 13, 1959 - C.S. File 49/107-3</p> <p>-----</p> <p>Found - Orig. Corner rock with "¼" chiseled on N. face. Fir tree, now 17", N.35°W., 7.2 ft. instead of 6.6 ft. Chopped this tree open and found scribing "¼". No trace of SE BT.</p> <p>Set I.P. with brass cap alongside original rock, cap marked: "County Surveyor's Office, 1959, T30S R5W ¼ $\frac{S\ 4}{S\ 9}$"</p> <p>Blaze and scribe new BTs: 21" D.Fir N.69°E., 16.5 ft. mkd. ¼ S4 CS BT. 15" D.Fir S.87°W., 41.7 ft. mkd. ¼ S9 CS BT.</p>
<p>BLM resurvey by Lynn Roseberry & James Jelley, under Group #662 -Surveyed Oct. 1967/June 1969 (DCSO rec Vol 38 Pg 15552)</p> <p>-----</p> <p>The ¼ sec. cor. perpetuated and recorded by Byron in 1959, monumented with an iron post, 1" dia., firmly set, projecting 4" above ground, alongside of which is the original basalt stone, cap properly marked. from which the remains of the original bearing trees</p> <p> A sawed Fir stump 17" dia., bears N.35°W., 10 lks. dist., with scribe marks ¼ visible on opened blaze.</p> <p>and bearing trees mkd. by Byron</p> <p> A root hole bears N.64°E., 23 lks. dist., with a down fir alongside, 20" dia., with scribe marks ¼ S4 CS visible on partially healed double blaze.</p> <p> A Fir 16" dia., bears S.87°W., 63½ lks. dist., with healed double blaze.</p> <p>and a new bearing tree</p> <p> A Fir 12" dia., bears N.21 ¾°E., 46½ lks. dist., mkd. ¼ S4 BT.</p>
<p>Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 3/15/2005 - C.S. File 67/10-13</p> <p>-----</p> <p>Found - 2½" BC on 1¼" O.D. iron pipe protruding 14" above ground in fallen N-S fence line (properly marked)</p> <p>continued next page</p>

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Stone with chiseled "¼" had rolled approx. 16 ft. down hill.
17" sawed Fir stump now 21" rotted D.Fir stump w/healed low blaze visible bears N.35°W., 6.6 ft. (agrees with 1969 BLM Rec.) 0BT
16" D.Fir now a 19" rotted D.Fir stump, no marks visible bears S.85½°W., 41.7 ft. (Dist. agrees with 1959 DCSO rec.) 1959
12" now 19" D.Fir with fully healed low single blaze bears N.21¾°W., 30.7 ft. (Rec. N.21¾°E., 30.7 ft.) 1969
New - Placed stone on South edge of BC/IP with chiseled "¼" facing North.
5" D.Fir double blazed & scribed "X CS BT" bears N.15°E., 4.0 ft.
12" D.Fir double blazed & scribed "¼ S9 CS BT" bears S.3½°E., 8.0 ft.
11" D.Fir double blazed & scribed "¼ S4 CS BT" bears N.60°W., 18.6 ft.
Note - Corner lies on steep south facing slope.
Compass decl. 17°E.

Fd. Ok by D. Edwards 1/2008 - M154-73