

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Oscar F. Thiel, under Contract #658 dated May 21, 1896 (DCSO records, Vol. 17 Page 7175)

-----  
A Fir 14" dia., which I marked  $\frac{1}{4}$  S on W. side for  $\frac{1}{4}$  sec.cor. from which

A Fir 14" dia., bears N.63°W., 20 lks. dist., mkd.  $\frac{1}{4}$  S BT.

A Fir 22" dia., bears S.80°E., 13 lks. dist., mkd.  $\frac{1}{4}$  S BT.

Doug. County Surveyors Office - James W. Byron, Deputy - S.A. Bilow - April 24, 1959 - C.S. File 49/107-5

-----  
Found - Both original BTs and corner tree. BTs check bearings and distances, show good scars. I do not open.

Corner tree previously opened, shows good scribing "S".

Set Brass cap alongside South edge of corner tree and mark:  
County Surveyor's Office, 1959

$\frac{1}{4}$  S9|S10 T30S R5W

New BT - 8" R.Fir bears N.46 $\frac{1}{2}$ °E., 45.5 ft. scribed  $\frac{1}{4}$  S10 CSBT

Doug. County Surveyors Office - James Byron, deputy - Mike Darby - Sept/Oct. 1963 - C.S. File 53/26-12

-----  
Found - Brass cap at corner. Corner tree, now dead. NW BT, now down.

8" Fir BT, N.46 $\frac{1}{2}$ °E., 45.5 ft, is OK.

New BT - 14" R.Fir S.43°W., 27.1 ft. scribed  $\frac{1}{4}$  S10 CS BT.

BLM resurvey by Lynn Roseberry & James Jelley, under Group #662 -Surveyed Oct. 1967/June 1969 (DCSO records, Vol. 38 Pages 15542-43)

-----  
The  $\frac{1}{4}$  sec. cor. monumented with the remains of the original corner tree, a Fir snag, 18" dia., with scribe mark S visible on opened blaze on W. face, from which the remains of the original bearing trees:

A root hole, bears N.63°W., 20 lks. with a down fir alongside 18" dia., no marks visisble.

and new bearing trees:

A Fir 11" dia., bears S.34 $\frac{1}{4}$ °E., 87 $\frac{1}{2}$  lks. mkd.  $\frac{1}{4}$  S10 BT.

A Cedar 13" dia., bears N.85 $\frac{1}{2}$ °W., 196 $\frac{1}{2}$  lks. mkd.  $\frac{1}{4}$  S9 BT

From this point, a local corner established by Byron in 1959, bears South, 0.02 chs. dist., monumented with an iron post, 1" dia., firmly set, projecting 8" above ground, with properly mkd. brass cap. (Cont. Next Page)

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which bearing tree mkd. by Byron in 1959:  
A Fir 8" dia., bears N.46°E., 67 lks. with scribe marks ¼  
S10 CS BT visible on partially healed blaze.  
and a bearing tree mkd. by Byron in 1963:  
A Fir stump 13" dia., bears S.45°W., 41 lks. dist., no  
marks visible.

Fd. OK, H. Johnstone, November 1986, M 103-1

BLM resurvey by Wayne L. Rogers, under Group #s 1000 and 1342  
- Surveyed, Aug. 1986 (DCSO records, Vol. 48 Pages 18349-50)  
-----  
The ¼ sec. cor., monumented with the original corner tree, a  
Fir snag, 18" dia., with scribe marks S visible on opened  
blaze on W. face, from which the remains of bearing trees  
mkd. by Roseberry and Jelley:  
A Fir snag 11" dia., bears S.34¼°E., 87½ lks. dist., with  
scribe marks ¼ S10 BT visible on partially healed  
blaze.  
A Cedar 30" dia., bears N.85½°W., 196½ lks. dist., with  
healed blaze.  
and a new bearing tree:  
A Fir 7" dia., bears N.54°E., 39 lks. mkd. ¼ S10 BT.  
From this point, a local corner established by Byron in 1959,  
bears South, 0.02 chs. dist., monumented with a 1959 brass  
cap,  
from which the remains of a bearing tree mkd. by Byron  
A Fir snag 10" dia., bears N.46°E., 67 lks. with healed  
blaze.  
and the remains of a bearing tree of no known record:  
A decayed Fir stump 32" dia., bears S.78½°E., 16 lks.  
dist., with scribe marks BT visible on opened blaze.

Fd. & used BLM resurvey by Wayne L. Rogers, under Group #  
1565, surveyed Aug. 1990/July 1991 (DCSO Records Vol. 50  
Page(s) 19122-19123)

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike  
- 3/15/2004 - C.S. File 67/6-5  
-----  
Found - Corner tree now rotted stump.  
Witness BC/IP missing.  
7" Fir N.54°E., 25.74' only standing BT

continued next page

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike  
- 3/29/2004 - C.S. File 67/10-42

-----  
Found - Orig. corner tree, a Fir 14" dia., now a rotted 1 ft. tall 20+ inch dia., broken Fir stump. Trunk of corner tree has fallen westerly on face.

1959 DCSO BC/IP is missing.

All B & D's measured from stump above:

Evidence of 2 orig. BTs fd:

A large uproot hole is fd. near B & D. for NW BT.

A 2½ ft. tall 32" dia., partly rotted & previously opened Fir stump with the scribing "BT" visible bears S.80°E., 8.6 ft. dist. (As per orig. rec. noted as tree not of rec. in 1986 BLM ren.)

From the 1959 DCSO renewal:

An 8" R.Fir now an 11 DBH 7 ft. tall rotted Fir snag with a fully healed double blaze bears N.47°E., 43.3 ft. dist. (Rec. N.46½°E., 45.5 ft; measured from missing 1959 BC)

From the 1963 DCSO renewal:

A 14" R.Fir now a 16" dia 1 ft. tall fir stump with evidence of a healed blaze in the bark only bears S.44°W., 28.3 ft. (rec. S.43°W., 27.1 ft.; measured from missing 1959 BC)

From the 1969 BLM renewal 2 then new BTs fd:

A fir 11" dia., now 12" dia. fallen & rotted fir snag rotted face no scribe bears S.33½°E., 56.3 ft. (rec. S.34½°E., 57.5 ft.)

A cedar 13" dia. now a 32" DBH I. Cedar with a fully healed double blaze bears N.85½°W., 129.7 ft. (as per rec.)

From the 1986 BLM renewal 1 then new BT fd:

A fir 7" dia., now a 14" DBH D.Fir with fully healed double blaze bears N.54°E., 25.7 ft. (per rec.)

New - All B & D's recorded in accessories fd are measured from a point very near the approximate center of the orig. corner tree stump. This position is referenced out & a hole is dug in the rotted stump remains. A 2½" dia., brass cap on a 1¼" O.D. x 31" long galvanized iron pipe is firmly set protruding approx. 6" above ground level at the above noted referenced position. Cap marked:

COUNTY SURVEYORS OFFICE

T 30 S

¼

S 9 | S 10

R 5 W

2004

cont. next page

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New BTs- 20" D.Fir bears S.58°W., 26.8 ft. double blazed & scribed "¼ S9 CS BT"  
16" D.Fir bears S.46°E., 32.2 ft. double blazed & scribed "¼ S10 CS BT"  
Decl. 16¾°E.

Fd. Ok by D. Edwards 1/2008 - M154-73  
Fd. Ok by D. Edwards 6/2012 - M163-70