

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Oscar F. Thiel, under Contract #658 dated May 21, 1896 (DCSO records, Vol. 17 Page 7178)

Set a yellow Fir post, 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor., mkd. ¼ S on W. face, from which
A Fir 12" dia., bears S.45°E., 9 lks. dist., mkd. ¼ S BT.
A Fir 10" dia., bears N.45°W., 33 lks. dist., mkd. ¼ S BT

Doug. County Surveyors Office - James W. Byron, Deputy - Mike Darby - Sept/Oct. 1963 - C.S. File 53/26-14

Found - Orig. 10" now 22" dead Fir N.45°W., 21.8 ft. We open and find good scribing.
Orig. 12" now 24" Fir S.45°W., 5.8 ft. shows good scars.

Set Brass cap at cor. mkd: County Surveyor's Office, 1963
¼ S4 | S3 T30S R5W

New BTs -14" R.Fir bears South 21.4 ft. scribed ¼ S4 CSBT.
12" Maple bears N.13°W., 48.3 ft. scribed ¼ S4 CSBT

Corner Fd. OK, by BLM resurvey by Lynn Roseberry & James Jolley, under Group #662 -Surveyed Oct. 1967/June 1969 (DCSO records, Vol. 38 Pages 15545-46)

BLM dependent resurvey by Wayne L. Rogers, Cadastral Surveyor, Under Contract # 1565, surveyed Aug. 1990/ July 1991 (DCSO records Vol. 50 Page(s) 19115-16)

The 1/4 sec. cor. of secs. 3 and 4, monumented with an iron post, 1¼ ins. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T30S

¼ S 4 | S 3

R5W

1963

from which the remains of the original bearing trees

A burned fir snag, 32 ins. diam., bears S. 45° E., 9 lks. dist., with healed blaze.

A decayed fir stump, size indeterminate, bears N. 45° W., 33 lks. dist., no marks visible. (Record, N. 35° W.) and the remains of bearing trees mkd. by James W. Byron, Deputy County Surveyor, in 1963

A fir, 25 ins. diam., bears South, 33 lks. dist., with healed double blaze.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A burned maple snag, 17" dia., bears N.13°W., 73 lks., with healed double blaze.
and a new bearing tree
A fir, 15" dia., bears S. 64° W., 91 lks., mkd. ¼ S4 BT.

DCSO-GIS Corner visitation - 3/14/2005 - Typed: 2/8/2011 - C.S. File 67/33-1

Monument - 1¼" IP/BC Comment - (needs) rehab

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Feb. 11, 2013 - C.S. File 67/38-16

Found - A 2½" dia., brass cap (properly marked) on a 1" I.D. iron pipe leaning approx. 1.8 ft. NW'ly from plumb and under the southerly end of a fallen and rotted 24" dia. Fir. (Accessories fd are checked for B & D from what would the plumb position of the fd. monument.)
A fir, 12" dia., now 32" dia., 8 ft. tall D.Fir snag with no clear blaze evidence visible; bears S.45°E., 5.9 ft. (as per rec.) OBT
A fir, 10" dia., now a rotted 14" dia., 2½ ft. tall fir stump with no blaze or scribe evidence remaining; bears N.45°W. 21.8 ft (as per rec) OBT
A 14" R.Fir now a 25" dia., approx. 12 ft. tall D. fir snag with a fully healed double blaze; bears South, 23.0 ft. (rec. South 21.8 ft., ground is steep, possibly a bad slope reduction) 1963
A 12" maple now a possible root-hole near record bearing & dist. 1963
A fir, 15" dia., now a 17" dia., 9 ft. tall D.Fir snag with a fully healed double blaze; bears S.64°W., 60.1 ft, (as per rec.) 1990-91
New - We clear away fallen fir over the monument. We re-plumb and stabilize monument which now is firmly set protruding 10" above ground.
A 10" dia., D.Fir scribed "¼ S3 CS" "BT" on a double blaze; bears N.61½°E., 20.1 ft.
A double trunk madrone, the 9" dia., southerly (and larger) trunk of which is scribed "¼ S4 CS" "BT" on a double blaze. The CRC of this madrone bears S.01°W., 15.9 ft.
A 10" dia., S.Pine scribed "¼S4CS" "BT" on a double blaze; bears N.71¾°W., 21.4 ft.
A 4" dia., (very pistol butt) S.Pine, scribed "X" "CSBT" on a high-low blaze; the CRC of which bears N.21½°W., 3.0 ft. continued next page

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Note - A steel corner post of mostly fallen fences running south and west is 1 ft. West of BC monument. Corner is on fairly steep north slope in young reprod. Forest of mostly D.Fir with some pine & madrone.
Compass decl. $15\frac{1}{2}^{\circ}$ E.