

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 and 11

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Oscar F. Thiel, under Contract #658 dated May 21, 1896 (DCSO records, Vol. 17 Page 7170)

A Maple tree, 12" dia., which I marked ¼ S on W. side for ¼ sec. cor., from which

A Maple 8" dia., bears N.88°W., 63 lks., mkd. ¼ S BT.

A Maple 8" dia., bears N.61°E., 7 lks., mkd. ¼ S BT.

John J. Markham, Jr. - For: Stomar Lumber Co. - Wit: W.E. Crawford; R.G. Boyd; J.L. Markham - March 20-25, 1958 - C.S. File 42/349-5

As determined by OBT:

12" Maple snag bears N.88°W., 41.6 ft.

15" Maple snag bears N.61°E., 4.6 ft.

At cor. point found 15" Maple scribed. I rescribed East face of Maple "¼ S and Set 3/4" x 30" Iron pipe, from which

7" Fir bears N.56°W., 41.6 ft. mkd. ¼ S10 BT.

12" Maple bears N.34°W., 63.0 ft. mkd. ¼ S10 BT.

10" Yew bears S.46°W., 71.0 ft. mkd. ¼ S10 BT.

Creek bears South 66.0 ft. dist.

BLM resurvey by Lynn Roseberry & James Jelley, under Group #662 -Surveyed Oct. 1967/June 1969 (DCSO records, Vol. 38 Page 15529)

The ¼ sec. cor. perpetuated and recorded by Markham, 1958, monumented with the remains of the original corner tree, a dead topped Maple, 16" dia., with scribe mark 4 visible on partially healed blaze on W., and ¼ S visible on E. faces, with an iron pipe, 3/4" dia., firmly set alongside, projecting 6" above ground, from which the remains of the original bearing trees:

A Maple root crown, size indeterminate, bears N.61°E., 7 lks. dist., no marks visible.

A Maple 16" dia., bears N.88°W., 63 lks. dist., no marks visible.

and the remains of bearing trees mkd. by Markham:

A Yew 13" dia., bears S.47½°W., 105 lks. dist., with scribe marks ¼ S10 BT visible on partially healed double blaze.

A root hole bears N.54°W., 63 lks. dist., with a down fir alongside, 7" dia., with scribe marks ¼ S10 BT visible on open decayed double blaze.

A Maple 15" dia., bears N.31 ¾°W., 95 lks. dist., with
(Cont. Next Page)

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

scribe marks $\frac{1}{4}$ S10 BT visible on partially healed double blaze.
and which a reference monument:
An Iron post, 28" long, 2 $\frac{1}{2}$ " dia., set 24" in the ground, for a reference monument, bears N.45°E., 10 lks. dist., with brass cap mkd. T30S R5W $\frac{1}{4}$ S11 RM 1969 and an arrow pointing to the corner.

Howard Johnstone, L.S. #498 - For: Roseburg Resources - Nov. 24, 1986 - M 103-1

Found - 24" Maple corner tree - rotten center.
1" Iron pipe on North side, 1969 Cadastral reference monument brass cap with iron pipe bears N.45°E., 6.6 ft.
15" Yew bears S.47 $\frac{1}{2}$ °W., 69.3 ft. scribing visible.
8" Fir bears N.54°W., 41.6 ft. down, scribe visible.
16" Maple bears N.31 $\frac{3}{4}$ °W., 62.7 ft. with rotten center.
New BTs -10" Fir bears N.39°E., 13.0 ft.
8" Fir bears N.25°W., 16.3 ft.

Fd. & used BLM resurvey by Wayne L. Rogers, under Group # 1565, surveyed Aug. 1990/July 1991 (DCSO Records Vol. 50 Page(s) 19120)

Fd. & used BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor and Robert H. Browning, Surveying Technician, under Group #1906, surveyed June/Aug. 1999. (DCSO rec. Vol. 53 page(s) 20513-4)