

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 540700

PRIMARY CORNER DESCRIPTION N 1/4 Cor. Sec. 2 only.

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6423)

-----  
Set 1/4 sec. post at proper distance, from which  
A B. Oak, 10" dia., bears N.37°E., 43 lks.  
A B. Oak, 12" dia., bears S.75°W., 84 lks.

G.L.O. Survey By Oscar F. Thiel, under Contract #658 dated May 21, 1896 (DCSO records, Vol. 17 Page 7182)

-----  
CORNER REPORT ONLY  
The Fire, that appears to have raged here about 8 years ago, has destroyed all the timber, growth of black oaks of about 2" dia., covers this spur.

B.L.M. Survey By Lynn M. Roseberry and James E. Jelley, under Group #662. Surveyed Oct. 1967/June 1969. (DCSO records Vol. 38 Page 15535)

-----  
The point for the 1/4 sec. cor. of sec. 2 only, T.30S., R.5W., is at midpoint on the N. bdy. of sec. 2.

Set an iron post 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

1/4 S 2  
T 30 S R 5 W  
1969

from which,  
An Oak, 6" dia., bears S.36°E. 27 lks. dist., mkd 1/4 S2 BT  
An Oak, 6" dia., bears S.67°W. 29 1/2 lks. dist., mkd 1/4 S2 BT  
From this point, the 1/4 sec. cor. of sec. 35 only, T.29S., R.5W., bears S.89°37'W., 5.36 chs. dist.

Fd. OK by W. Rogers, April 2000 - M134-52