

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 17 Page 7136  
-----

Set ¼ sec. post from which  
A B.Oak 14" dia., bears N.67°W., 219 lks. dist.  
A B.Oak 24" dia., bears S.45°E., 125 lks. dist.

H. L. Northcraft - T. Schattenkerk; H. Rishel; R. Wenuer - May 1950 - C.S. File 40/281  
-----

Found - 24" B.Oak S.45°E., 125 lks. Cut out the upper blaze and found old scribe "¼ S" intact.  
14" B.Oak N.67°W., 219 lks. was gone.  
Set an Oak stake at the corner and mkd. two new trees:  
30" B.Oak N.50°E., 79 ft. mkd. ¼ S25 BT - 1581  
14" W.Oak N.63°W., 97 ft. mkd. ¼ S26 BT - 1581  
(These corners hve A. Boyer's #1581, not authentic)

Doug. County Surveyors Office - James Byron, Deputy - Mike Darby; Jim halterman - Nov/Dec. 1963 - C.S. File 53/26-39  
-----

Found - Orig. 24" now 36" Oak S.45°E., 82.5 ft. shows good reverse scribing on section cut from tree.  
Orig. NW BT not found.  
Set Brass cap at cor. mkd: County Surveyor's ¼ S26 | S25 T30S R5W Office, 1963.  
New BT - 9" W.Oak N.51°E., 25.9 ft. scribed ¼ S25 CS BT.  
We do not find stake set at corner. We find 14" W.Oak N.59°W., 96.0 ft. not N.63°W., 97.0 ft., shows scribing.

Doug. County Surveyors Office - Randall W. Smith; Stephen J. Flause - Jan. 6, 1986 - C.S. File 62/31-16  
-----

Found - A recently set 5/8" Iron rod, protrudes 4" above ground. Source unknown.  
DCSO I.P. with brass cap out of ground under ½" soil mkd. in 1963.  
Orig. BT, 24" now 40" Oak with a rotted burnt out blaze bears S.45°E., 82.5 ft. (agrees w/rec) 1963 BT tag on tree.  
30" B.Oak gone, cat work in area.  
14" W.Oak possibly - down, burnt and rotted in slide area. No scribe found. Orig. position indeterm-able.  
9" W.Oak gone, depression in ground bears N.51°E., 25.9 ft. (agrees well with rec.)

(Cont. Next Page)

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 26 and 25

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Position of 5/8" I.Rod accepted as corner location. This position agrees with orig. SE BT and NE BTs per 1963 visit with depression in ground. BC/IP found out of ground 4" from iron rod.

Reset DCSO 1" x 36" BC/IP protrudes 7" above ground with 5/8" I.R. protruding 5" above ground along North edge of brass cap mkd. with RESET 1986.

New BTs -19" D.Fir double blazed and scribed "¼ S25 CS BT" bears S.77½°E., 55.0 ft.

17" W.Oak double blazed and scribed "¼ S25 CS BT" bears N.21°E., 27.5 ft.

40" W.Oak double blazed and scribed "¼ S26 CS BT" bears S.73°W., 119.8 ft.

Corner lies on a NW slope. Dirt road approx. 125 ft. from corner.

Fd. Brass Cap & BT's by Raymond Brown, 10/93 - M 119-4  
Fd. Ok by R. Brown, 3/2009 - M157-28