

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 641100

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. Sec. 1 only, T31-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W.H. Byars, under contract # 456 dated July 28, 1882 (DCSO rec. Vol. 17 Pages 7163-64)

-----  
Set a stone 16x12x6 ins. for the ¼ sec. corner marked ¼ on the N side and from which  
A Fir 26" dia., bears S.30°E., 50 lks. dist. mkd. ¼ S BT.  
A Laurel 6" bears N.55°W., 21 lks. dist. mkd. ¼ S BT.

-----  
Doug. County Surveyors Office - James Byron, Deputy - Mike Darby; Jim Halterman - Nov/Dec. 1963 - C.S. File 53/26-44

-----  
Found - Orig. 6" now down 10" Laurel N.55°W., 13.9 ft. We open and find good scribing "BT".  
Orig. SE BT shows old axe work  
Corner stone not found. Corner is on steep East slope.  
Set 3/4" Iron rod at corner and new BTs as follows:  
7" R.Fir bears N.20°W., 16.8 ft. scribed ¼ S36 CS BT.  
8" R.Fir bears S.35°W., 17.2 ft. scribed ¼ S1 CS BT.

-----  
BLM resurvey by Jelley; Roseberry; and Brooks, under Group #'s 320 and 614 - Surveyed, June 1966/May 1968 (DCSO records, Vol. 35 Pages 14355-56)

-----  
Found 1/4 Cor. established by Byars in 1882, perpetuated and recorded by Byron in 1963, monumented with an iron rod, 1/2" dia., protruding 6" above ground, firmly set, from which the original bearing trees:

A root hole bears N.55°W., 21 lks. dist., alongside of which is a fallen Madrone 10" dia., with illegible scribe marks visible on opened and rotted blaze.

A Fir 36" dia., bears S.30°E., 50 lks. dist., with old axe marks visible.

and bearing trees mkd. by Byron:

A Fir 7" dia., bears N.25°W., 25 lks. dist., with a healed blaze.

A Fir 10" dia., bears S.35°W., 25 lks. dist., with a healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, directly over the iron rod, with brass cap mkd:

-----  
¼ S 1  
T 31 S R 5 W  
1967