

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 700100

PRIMARY CORNER DESCRIPTION CC Tsp cor S 36, T30-5; S 1, T31-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Butler Ives and Geo. Hyde, under Contract #39 dated Jan. 4, 1854 (DCSO records, Vol. 16 Page 6984)

Set a post, Cor. of Tps. 30 and 31 S., Rs. 4 & 5 W., from which

- A Fir 14" dia., bears N.34°E., 4 lks. dist.
- A Fir 11" dia., bears S.60°E., 17 lks. dist.
- A Laurel 8" dia., bears S.83°W., 33 lks. dist.
- A Live Oak 7" dia., bears N.50°W., 7 lks. dist.

GL0 resurvey by Wm. Thiel under Contract #535 dated Feb. 5, 1889 (DCSO records, Vol. 17 Page 7016)

The post set for this Cor. is entirely gone, but all the bearing trees are standing. I restore this Cor. by setting a Laurel post, 4½ ft. long 4" sq., 24" in the ground, marked T31S R5W S1 on SW., T30S R5W S36 on NW., faces with 6 notches on N., S., and W. edges, from which

- A Live Oak 8" dia., bears N.50°W., 7 lks. dist., mkd. T30S R5W S36 BT.
- A Laurel 10" dia., bears S.83°W., 33 lks. dist., mkd. T31S R5W S1 BT.

These are the old bearing trees, which I re-mark, as the old marks are overgrown and quite dim.
This corner stands in a thicket of Laurels, Firs and Live Oaks.

Doug. County Surveyors Office - April 11, 1957 - C.S. file 47/175-3

Found - Remains of old BTs to NE and SE badly rotted but scribe marks plainly visible.

Clump of Laurel saplings & depression in ground showing location of old tree fit for bearing and distance to laurel bT in SW quadrant.

Set an I.Pipe 1" dia. with brass cap, mkd: County Surveyor's

T30S R5W	T31S R4W
36	
T31S	1
	1957
	Office

from which

- 12" Fir S.18°E., 18.9 ft. mkd. T31S R4W S6 CS BT.
- 12" Fir N.3°W., 28.2 ft. mkd. T30S R5W S36 CS BT.
- 6" Live Oak S.29°W., 33.0 ft. mkd. T31S R5W S1 CS BT.

continued next page

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 700100

PRIMARY CORNER DESCRIPTION CC Tsp Cor S.36, T30-5; S.1, T31-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by Jelley, Brooks & Roseberry under Group #'s 320 and 614 - Surveyed June 1966/May 1968 (DCSO records, Vol. 35 Page 14355)

Found 1957 Co. cap with an iron post, firmly set, from which remaining original bearing trees:
A burned fir stump 16" dia., bears N.34°E., 4 lks. dist., with scribe mark T visible on rotted blaze.
A burned fir stump 18" dia., bears S.60°E., 17 lks. dist., with scribe marks R T31S S BT visible in reverse on overgrowth lying on ground.
and bearing trees mkd. by Co. Surveyor in 1957
A Fir 17" dia., bears S.18°E., 28 lks. dist., with a healed blaze.
A live Oak 8" dia., bears S.29°W., 48 lks. dist., with a healed double blaze
A Fir 18" dia., bears N.7°W., 43 lks. dist., with a healed double blaze.
Add marks BLM 1966 to Brass cap.

Corner Fd. OK, BLM survey by Berry and Akin under Group #800 - Surveyed Sept. 1972/June 1973 (DCSO rec. Vol. 38 Pg 15652)

Fd. OK, April 1996 by Ken Hoffine - M 123-69

DCSO-GIS Corner visitation - 4/8/2004 - Typed: 2/8/2011 - C.S. File 67/33-1

Monument - 1¼" Comment - needs renewal

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2872, surveyed April 2017/Oct. 2019- (DCSO records Vol. 59 Page 23832-3)

The cor. of T30 & 31S R5W only, bears S.0°22'02"E., 2309.77 ft.; monumented with an iron post, 1½" dia., firmly set projecting 11" above ground, with a brass cap (properly) mkd. from which the BTs mkd. by Byron in 1957, reported by Berry and Akin, Jr. in 1972
A fir, 34" dia., bears S.18°E., 18.5 ft., with a healed double blaze.
A fir, 28" dia., bears N.7°W., 28.4 ft., with a healed double blaze.
and a BT mkd. by person(s) unknown
A fir, 14" dia., bears N.9¼°W., 12.0 ft., with a healed double blaze.
and a new BT
A fir, 31" dia. bears S.54°W., 59.6 ft mkd. T31S R5W S1 BT