

PRIMARY CORNER DESCRIPTION NW Cor. Merryman DLC #49

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Original - Elliott Bowman and Josiah Burnett under Contract dated Sept. 24, 1855

Set a post for N W corner, from which
A W.Oak 8" dia., bears S.37°E., 37 lks.
A B.Oak 18" dia., bears N.85°W., 9 lks.

Jesse W. Cole, Deputy - For: Mynett Estate - Wit: Cassuis Mynatt; Cecil Black; Ralph Johnson - Oct. 8, 1915 - Vol. 2 Pg. 240-241; C.S. File 7/27

Renew from original BTs, both standing and alive.
Set Oak post 4" x 4" x 3½".

Douglas Co. Surveyors Office - Ben B. Irving, DCS - Wit: Jim Byron; Ray Irving; Joh Fee - Oct. 26, 1953 - Filed County Road plans Riddle Loop Road #39

Set 1" Iron pipe brass cap from old BT stump for corner mkd. "County Surveyors Office DLC 49 1953" and set pipe 24" in ground. Stumps of orig. BT rotted but show evidence of having been chopped out. Checked original field notes. Corner is in old fence corners.
New BTs -12" Fir N.72½°E., 17.0 ft., blazed and scribed DLC 49 CS BT.
12" Fir, West, 30.0 ft. blazed and scribed DLC 49 CS BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Jim Halterman - Nov/Dec 1963 - C.S. File 53/40-4

Found - Brass cap at corner.
Also, now 14" Fir N.72½°E., 17.0 ft. shows good scars.
West bearing tree down.
New BT -6" Laurel bears S.66°W., 10.5 ft. scribed NW DLC 49 CS BT.

Douglas Co. Surveyors Office - John M. Powell; Frank Jones; W. Penley - Sept. 11, 1969 - C.S. File 53/40-110

Found - Brass cap buried & badly bent, broken off while trying to straighten. Deposit broken cap alongside new brass cap.
14" D.Fir now stump, N.72½°E., 17.0 ft. scribe fd.
No trace of SW bearing tree.
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION NW Cor. Merryman DLC #49

| Alias | Description |
|-------|-------------|
| | |
| | |
| | |
| | |

Set new brass cap at cor. mkd. County Surveyors T 30 S R 6 W
Office, 1969 /NW DLC Cor 49

New BTs -38" W.Oak, South, 171.8 ft. mkd. NW DLC #49 CS BT.
42" W.Oak N.83½°E., 124.0 ft. mkd. NW DLC #49 CS BT.
This corner lies about 65 ft. N. and 30 ft. E. of small ravine.

Douglas Co. Surveyors Office - Stephen Flauser; T.R. Franssen
- April 29, 1991 - C.S. File 64/15-2

Found - A 2½" dia. 1969 DCSO BC on a 1 3/8" O.D. I.P. firmly set, leaning approx. 0.35 ft. southwesterly from plumb and protruding 12" above ground.
The BC/IP monument described in 1953 renewal is found loose on ground surface 4 ft. southwest from above found monument. I.P. is broken, remaining pipe and BC measures approx. 12" long.
(Accessories are checked from plumb position of BC monument.)
(No evidence of original BTs remains, same trees, Cole, 1915)

Found - 12" Fir now burned fir bark and roots in a stump hole bears West 30.0 ft. as per record.
NE BT removed by road work.
(No BTs described as by Byron, 1963 are found.)
38" W.Oak now a 39" DBH B.Oak with the scribing "C49" visible in a partially healed double blaze bears South, 171.8 ft. as per record, Powell, 1969.
42" W.Oak now a 44" DBH B.Oak with a fully healed double blaze bears N.83½°E., 124.0 ft. as per record.

The found monument from 1969 is returned to plumb position.
Broken monument from 1953 is deposited on west edge of above monument.

New BTs -An 8" DBH Madrone scribed NW DLC 49 CS BT on a double blaze bears S.61°E., 41.2 ft.
A 10" DBH Jeffrey Pine scribed NW DLC 49 CS BT on a double blaze bears S.30°E., 33.6 ft.

In scrub area northwest from open pastures.

Fd. OK Oct. 1999 by K. DeGroot - M133-37
Found OK by K. DeGroot, Dec. 2000 - LP 2000-0092 A&B
Fd. Ok by R. Quimby, 4/2008 M146-73