

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 212700

PRIMARY CORNER DESCRIPTION So. Sec. Cor. 31 & 32 only, T29-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Fred C. Mensch under Contract #757 dated Sept. 14, 1904 - (DCSO records, Vol. 15 Page 6498)

(Point on Tp. bdy., 11.70 chs. S.89°36'E., of the cor. of secs. 5, 6, 31 and 32,)

Set an ironstone 24 x 14 x 12 ins. 18" in the ground for closing corner of secs. 31 and 32, marked CC on N. with 5 grooves on E. and 1 groove on W. face, from which

A R.Fir 7" dia., bears N.63°E., 45 lks. dist., mkd.
T29S R6W S32 BT.

A R.Fir 6" dia., bears N.45°W., 20 lks. dist., mkd. T29S
R6W S31 BT.

I destroy marks on former corner and bearing trees referring to these secs.

John H. Markham, Jr. - For: Stomar Lbr. Co. - Aug/Oct. 1956
C.S. File 42/190-5

Found - 11" Fir bears N.63°E., 30.0 ft., O.B.T, found scribe.

6" Fir snag, bears N.45°W., 13.0 ft., O.B.T., found scribe.

At corner point, found large stone and Set 3/4" x 20" Iron pipe from which

20" Yew wood bears N.49°E., 44.6 ft. mkd. S32 T29S R6W BT.

13" Cedar bears S.2°W., 31.8 ft. mkd. S31 X BT.

60" Fir bears N.65°W., 34.4 ft. mkd. S31 T29S R6W BT.

Corner lies in a E-W saddle.

BLM resurvey by Thielsen and White under Contract #'s 348 and 350 - Surveyed July 1958/August 1959 - (DCSO records, Vol. 30 Page 12813)

The original closing corner established by Mensch in 1904, bears N.0°02'W., 33 lks., monumented with a basalt stone, 24x14x12 ins. 16" in the ground, firmly set, mkd. CC on N. face, from which the remaining original bearing tree:

A Fir 10" dia., partially dead, bears N.61½°E., 45 lks. mkd. R6W S32 on open blaze. (Rec. N.63°E.)

In order that this point will not be lost

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd:

 C C
T 29 S | R 6 W
 S 31 | S 32
 S 5
 T 30 S

1958

(Cont. Next Page)

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 212700

PRIMARY CORNER DESCRIPTION So. Sec. Cor. 31 & 32 only, T29-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

from which new bearing trees
A Fir 20" dia., bears N.79°E., 61 lks. mkd. T29S R6W S32
CC BT.
A Fir 45" dia., bears N.53½°W., 78 lks. mkd. T29S R6W S31
CC BT.
Bury original stone alongside the iron post.

Doug. County Surveyors Office - Gary Langlitz; Peter Earle -
Feb. 20, 1974 - C.S. File 56/43-20

CORNER REPORT ONLY
Found corner in good condition. I Do Not Renew
Corner lies in bottom of draw, course West, approx. 200 ft.
South of a fairly new logging road.

Corner Fd. OK, Jelley & Rogers under Contract #1024 and 1039
- Surveyed 1980 - DCSO records, Vol. 42 Pages 16565-66

BLM resurvey by Wayne L. Rogers, under Group #1030 - Surveyed
Aug/Sept. 1980 (DCSO records, Vol. 45 Pages 17259-60)

Found original closing corner and 1958 brass cap from which
the remains of the original bearing trees
A Fir 18" dia., bears N.61½°E., 45 lks. with healed blaze.
and bearing trees mkd. by Markham in 1956
A Yew 23" dia., bears N.51½°E., 67½ lks. dist., with
scribe marks S32 T29S R6W BT.
ACedar 18" dia., bears S.5½°W., 48 lks. with healed double
blaze.
and bearing trees by Thielsen and White
A Grand Fir 25" dia., bears N.79°E., 61 lks. with healed
blaze.
A Fir 50" dia., bears N.53½°W., 78 lks. dist., with scribe
marks T29S R6W S31 BT.
Add the marks AM to the brass cap.

(At a point .35 chs., S.0°51'W.)
Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the
ground, with brass cap mkd: T 29 S R 6 W
C C
S 31 S 32
S 5
T 30 S R 6 W
1980

from which new bearing trees
(Cont. Next Page)

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 212700

PRIMARY CORNER DESCRIPTION So. Sec. Cor. 31 & 32 only, T29-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Fir 8" dia., bears N.64¼°E., 54 lks. mkd. T29S R6W S32
CC BT.
A Fir 6" dia., bears N.72 3/4°W., 88½ lks. mkd. T29S R6W
S31 CC BT.

Survey by Howard Johnstone, - For: Roseburg Resources Inc. -
Jan. 23, 1990 - C.S. File 63/104-4 & 63/104-5

Found - 1980 Cadastral brass cap on iron pipe.
6" Fir N.72 3/4°W., 58.4 ft. high stumped. Gone.
(1980 BLM)
8" Fir N.64¼°E., 35.6 ft. good face, high stumped.
(1980 BLM)
23.1 ft. North to AM-CC brass cap. (1958 BLM)
Tied corner to remaining BTs for the AM-CC:
50" D.Fir stump bark scribed, N.36°W., 67.0 ft.
18" Fir healed face, N.37°E., 45.5 ft.
25" W.Fir healed face, N.54°E., 49.6 ft.
Corner lies in NE corner of 1989-90 clear cut unit logging
all around the corner. About 200 ft. South of road.

DCS0-GIS Corner visitation - 8/10/2004 - Typed: 2/1/2011 -
C.S. File 67/33-1

Monument - GLO/BLM 2.5" BC/IP
Comment - (needs) rehab

David Edwards - For: Roseburg Resources Co - 3/2011 - M162-22

Condition report
Fd. BLM cap on ground.
Reset per Johnstone rehab. C.S. 63/104
AM CC cap N.0°51'E., 23.1'
20" Fir N.37°E., 45.5'
25" Fir N.54°E., 49.6'
Capped fir stump N.64¼°E., 35.6'