

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 253700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. Sec. 32 only, T29-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6460)

Set ¼ sec. post at proper distance, from which
A B.Oak 6" dia., bears N.65°W., 84 lks.
A W.Oak 6" dia., bears S.75°W., 34 lks.

GL0 resurvey by Fred Mensch, under Contract #757 dated Sept. 14, 1904 (DCSO records, Vol. 15 Page 6510)

The ¼ cor. being partially obliterated, I reestablish this corner in its original position, as follows:
Set a slate stone 14x10x6 ins. 9½" in the ground for ¼ sec. cor. mkd. ¼ on N. face, from which
A W.Oak 6" dia., bears N.46°W., 13 lks. mkd. ¼ S32 BT.
A W.Oak 9" dia., bears S.40°W., 42 lks. mkd. ¼ S5 BT.

John H. Markham, Jr. - For: Stomar Lumber Co. - Aug/Oct. 1956
C.S. File 42/190-3

At a point on township line, 2634 ft. West of SE corner of Sec. 32, and 2451.5 ft. East of SW corner of Sec. 32, I set a 1" truck axle with flange up for ¼ corner. From which
A 40" W.Oak bears East 14.7 ft. mkd. ¼ S32 BT.
A 7" Fir bears West, 13.3 ft. mkd. ¼ S BT.
North ¼ cor. Sec. 5 bears West, 635.5 ft.
Corner lies along E-W fence.

BLM resurvey by Thielsen and White under Group #'s 348 and 350 - Surveyed July 1958/Aug. 1959 - (DCSO records, Vol. 30 Page 12812)

Point for the ¼ sec. cor. of sec. 32 only, at midpoint in departure on the S. bdy. of sec. 32.
Set an iron post, 28 ins. long, 2½ ins. diam., 20 ins. in the ground, with brass cap mkd: ¼ S 32
T 29 S R 6 W
1958

from which
An Oak 30" dia., bears N.83°W., 114 lks. mkd. ¼ S32 BT.
Raise a mound of stone, 4 ft. base, 2½ ft. high, N. of Cor.

BLM resurvey by Jelley and Rogers, under Group #'s 1024 and 1039 - Surveyed April/Oct. 1980 (DCSO records, Vol. 42 Pages 16564)

(Cont. Next Page)

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 253700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. Sec. 32 only, T29-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

At 27.70 chs., N.89°01'W., from sec. cor. for 4 & 5 only, T30-6, - the 1/4 Section corner of sec. 32 only, erroneously established by Thielsen and White in 1958, bears North, 0.03 chs. dist., monumented with an iron post, 2½" dia., set, marked and witnessed as described in the official record. I remove the iron post and destroy the marks on the bearing tree.

David Edwards - For: Roseburg Resources Co - 3/2011 - M162-22

Set south ¼ corner sec. 32 only at midpoint in departure between closing corners to the east & west.

Set - 5/8"x30" steel rebar with 2½" diam. alum. cap stamped per BLM Manual and also stamped "ROSEBURG RESOURCES CO." - "LS 2339" and "2011"

A 4" dia. Tanoak bears N.42°E., 50.2 ft.

A 32" dia. Fir bears N.75W., 23.7 ft.

A 6 ft steel post is set 2 ft North.

BTs were scribed according to BLM Manual, measured to center of tree at root crown.