

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 4 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, Under Contract #56, dated March 1855 (DCSO records Vol. 17 Page(s) 7218)

Set quarter sec. post, from which a
Red Fir 3" dia., bears S.80°E., 48 lks. dist.
Red Fir 3" dia., bears N.50°E., 41 lks. dist.

John H. Markham, Jr. - For: Stomar Lumber - Wit: George Vaughn - July 16, 1951 - C.S. File 40/277-6

Found - A Fir 11" dia., bears N.50°E., 27.0 ft., fd. scribe.
At corner point set 1" x 30" I.P., from which
15" Fir bears N.3°W., 34.0 ft. mkd. ¼ S BT
33" Fir bears S.30°E., 15.0 ft. mkd. ¼ S S9 BT.
A fence running East and West bears North, 80 ft.

DCSO, Feb. 24, 1964, C.S. File 53/40-28

We find cor. as recorded except I do not believe an orig. BT was fd. Hicks may have renewed this cor. (Added 7/31/2012)

BLM resurvey by Lynn Roseberry under Group #649, Survey Aug/Sept. 1967 (DCSO records, Vol. 35 Pg. 14351)

The ¼ sec. cor. determined at record bearing and distance from the remaining original bearing tree:

A Fir 38" dia., bears S.80°E., 48 lks. dist., with scribe marks ¼ S BT visible on opened blaze on SE. side of tree. (A count of annual growth rings and size of tree shows it to be the original bearing tree.)

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd: T 30 S R 6 W

¼ $\frac{S\ 4}{S\ 9}$
1967

from which a new bearing tree

A Fir 8" dia., bears N.38¾°E., 73½ lks., mkd. ¼ S4 BT.

From this point a locally established cor., bears N.68°E., 0.375 chs. dist., established and recorded by Markham in 1951, monumented with an iron pipe 1" dia., protruding 6" above the ground, firmly set, from which bearing trees mkd. by Markham:

A sawed Fir stump 18" dia., bears N.2 ¾°W., 51½ lks., with illegible scribe marks visible on burned blaze.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 and 9

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

A Fir 38" dia., bears S.26°E., 25 lks. dist., with scribe marks ¼ S9 BT visible on N. side of tree on bark blaze. This tree was opened on the SE. side and original 1855 scribe marks were found.

Douglas Co. Surveyors Office - Stephen J. Flause - Dennis D. Lee - July 20, 2012 - C.S. File 67/36-19

Found - 1 3¼" dia., brass cap (properly mkd) on a 2½" OD iron pipe firmly set and protruding 9" above ground. 1967

1" I.D. iron pipe (determined to be erroneous ¼ corner monument by 1967 BLM resurvey) is firmly set, protruding 6" above ground; bears N.68°E., 24.5 ft. (agrees well with rec. N.68°E., 0.375 chs) 1951

A 15" fir now an 18" dia., 6 ft. tall sawn fir stump which is now very rotted and shows no clear blazes or scribing; bears N.26°E., 48.0 ft. (agrees with tie computed from BLM rec.) 1951

Evidence of one orig. BT (as determined by BLM) A R.Fir 3" dia., now a 38" dia., D.Fir with a previously opened single blaze scribed "¼ S BT" (blaze surface is twisted and faces approx. N.35°E.) bears S.80°E., 31.7 ft. (as per rec). Bad blaze face direction may be due to very small orig. dia. We check thoroughly for evidence of another OBT but find none.

A fir, 8" dia., now a 17" dia., D.Fir with a fully healed, low, small, single blaze; bears N.38¾°E., 48.5 ft. (as per rec.) 1967

New - A 10" DBH D.Fir scribed "¼ S9 CS" "BT" on a double blaze; bears S.69°W., 13.7 ft.

A 9" DBH I.Cedar scribed "¼ S4 CS" "BT" on a double blaze; bears N.8½°W., 36.4 ft.

Note - Monument is southerly slope just off top of E'stly-W'stly running ridge. Dirt Rd. on ridge-top is approx. 65 ft. north of corner. Area is in mixed age forest of fir, cedar, madrone & pine.

Compass decl. 15½°E.