

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 346700

PRIMARY CORNER DESCRIPTION S. 1/4 Cor. Sec. 33 only of T26-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Thielsen and White, under Group #'s 348 and 350. Surveyed, July 1958/Aug. 1959 (DCSO records, Vol. 30 Page 12824)

Point for the ¼ sec. cor. of sec. 33 only, at midpoint on the S. bdy. of sec. 33.

Set an iron post, 28 ins. long, 2½ ins. diam., 20 ins. in the ground, with brass cap mkd:

¼ S 33
T 29 S R 6 W
1958

from which

A Fir 9" dia., bears N.38½°E., 56 lks. dist., mkd. ¼ S33 BT.

A Fir 10" dia., bears N.27°W., 47 lks. dist., mkd. ¼ S33 BT.

BLM resurvey by Jelley and Rogers, under Group #'s 1039 and 1024. Surveyed April/Oct. 1980 (DCSO records, Vol. 42 Page 16561)

Point for the 1/4 sec. cor. of sec. 33 only, at midpoint on the S. bdy. of sec. 33.

From this point, the ¼ sec. cor. of sec. 33 only, erroneously established by Thielsen and White in 1958-59, bears S.52°13'W., 0.15 chs. dist., monumented with an iron post, 2½" dia., set mkd. and witnesses as described in the official record.

I remove the iron post, and at the corner point

Reset the iron post, 28" long 2½" dia., 24" in the ground, with brass cap mkd:

T 29 S R 6 W
1/4 S 33
1958
1980

from which bearing trees mkd. by Thielsen and White

A Fir 17" dia., bears N.33½°E., 41½ lks. dist., with healed blaze.

A Fir 16" dia., bears N.45¼°W., 46½ lks. dist., with healed blaze.