

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Under Contract #56, dated March 1855 (DCSO records Vol. 17 Page 7209)

B.Oak, 18" dia., bears N.58°W., 193 lks. dist.
Ash 4" dia., bears N.28°E., 107 lks. dist.
Pine 20" dia., bears S.6°W., 371 lks. dist.
Ash 18" dia., bears S.61°E., 538 lks. dist.

J. W. Cole, Surveyor - Wit: Ben B. Irving - Jan. 23, 1924
(Record source not found - see "Old" cor. Bk. Pg. 149)

Set an I.Pipe 1½" x 40" and mound of rock from remains of stump of old Oak BT, bears N.58°W., 127.4 ft. A 40" Pine BT bears South 246.6 ft. No other trees to be found and I Set corner so that bearing and distance to Oak checked but only distance to Pine would check.

Marked New BTs

A W.Oak 12" dia., bears N.19°00'W., 92.6 ft.
A B.Oak 15" dia., bears S.65°00'E., 355.0 ft.
An Ash 8" dia., bears N.21°00'E., 62.0 ft.
An Ash 8" dia., bears S.24°15'W., 264.0 ft.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Mike Darby; Jim Halterman - Dec. 1963/Jan. 1964 - C.S. 53/40-11

Found - All BTs as recorded except we do not find SE BT.
Do not find I.Pipe or Mound. Corner is in old field.

Set Brass cap at cor. mkd: County Surveyors S28|S27
Office 1963 S33|S34 T30S R6W

New BT - 14" B.Oak bears S.30°W., 253.3 ft. scribed S33 T30S R6W CS BT.

Douglas Co. Surveyors Office - Randall Smith; Stephen Flause; Terrie Franssen - April 24, 1991 - C.S. File 64/13-26

Found - 2½" dia. DCSO brass cap on an 1½" O.D. x 36" long I.P., tipped over, flanges still in ground, good for position.

12" now 25" dia., W.Oak with a fully healed double blaze, bears N.19°W., 92.6 ft.

8" now 14" dia., Ash with previously opened blaze, illegible scribe marks visible, bears N.21°E., 62.0 ft.

8" now 13" dia. 8" high broken Ash stump, no blazes or scribing visible, bears S.24¼°W., 264.0 ft.

No other BTs found. (Cont. Next Page)

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Position of flanges referenced, BC/IP removed and straightened. BC/IP returned to referenced position, now protrudes 2" above ground. Marks "RESET 1991" are added to Brass cap.

New BTs -18" dia. B.Oak double blazed and scribed "T30S R6W S28 CS BT" on northeasterly trunk, bears N.57½°W., 110.3 ft. to center of scribed trunk at base.

18" dia. Ash double blazed and scribed "T30S R6W S28 CS BT" on southeasterly trunk bears N.26°W., 42.4 ft. to center of scribed trunk at base.

No reasonable trees to the South.

Found OK by K. DeGroot, Oct. 1999 - M133-37

Found OK by K. DeGroot, Dec. 2000 - LP 2000-0092 A&B

Fd. Ok by R. Quimby, 4/2008 M146-73

Fd. BC by R. Quimby 7/2011 - M157-48