

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, Under Contract #56, dated March 1855 (DCSO records Vol. 17 Page 7211)

-----  
Set quarter sec. post, from which  
B.Oak 10" dia., bears N.75°W., 22 lks. dist.  
W.Oak 10" dia., bears S.85°W., 29 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Jim Halterman - Dec. 1963/Jan. 1964 - C.S. 53/40-10

-----  
Found - Orig. 10" now 18" B.Oak N.75°W., 14.5 ft. open & find good scribing.  
Orig. 15" now 24" W.Oak S.85°W., 21.1 ft. Not S.85°W., 19.1 ft. We open & find old axe work.

Set Brass cap at cor. mkd: County Surveyors  $\frac{1}{4}$   $\frac{S15}{S22}$ T30S R6W  
Office, 1963

New BTs - 18" B.Oak bears S.9°E., 32.8 ft. scribed  $\frac{1}{4}$  S22 CS BT.  
22" W.Oak bears N.54°W., 31.2 ft. scribed  $\frac{1}{4}$  S15 CS BT.

Wire fence fastened to orig. NW BT.

Fd. and used, BLM survey, subd. of sec. 15 by Wayne Rogers, 1988, under Group #1434 (DCSO records Vol. 48 Page(s) 18638-39)

Mark Smalley for Roseburg Forest Products, May 4, 1995 C.S. File 63/161-25.

-----  
Found - 1963 D.C. Surveyor's Office iron pipe with brass cap 8" above ground.  
- 26" Oak, N.56½°W., 47 lks. Good, healed face.  
- 24" Oak, N.75°W., 14.5 ft. Poor, face chopped out.  
- 24" Oak, S.9°E., 32.8 ft. Good, healed face.  
- 28" Oak, S.80°W., 33 lks. Good, face chopped out.

New Accessories -  
- 14" Oak, S.28°E., 40.2 ft. scribed " $\frac{1}{4}$  S BT"

Found OK by B. Shaner, May 2000 - M132-32 & CS65/30-11A  
Fd. Ok by Greg Lang 9/2007 - M154-46