

PRIMARY CORNER DESCRIPTION Sec Cor for 34 & 35; 3 & 2, T31-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, Under Contract #56, dated March 1855 (DCSO records Volume 17 Page 7193)

-----

Set post, cor. to secs. 34, 35, 2 and 3, from which

- A W.Oak 22" dia., bears N.80°E., 215 lks.
- A B.Oak 15" dia., bears N.13°W., 107 lks.
- A W.Oak 18" dia., bears S.15°W., 66 lks.
- A B.Oak 10" dia., bears S.63°E., 230 lks.

Doug. County Surveyors Office - James Byron - For: BLM  
May 12, 1969 - C.S. File 54/86; M 37-62

-----

Corner set from survey at proportionate distance.

Set Brass cap at cor. mkd: County Surveyor's Office 1969

T 30 S R 6 W	S 34	S 35
	S 3	S 2
T 31 S R 6 W		

New BTs -22" B.Oak, S.36°30'E., 70.0 ft. mkd. "T31S R6W S2 CS BT".

- 7" Cedar N.81°W., 37.6 ft. mkd. "T30S R6W S34 CS BT.
- 23" D.Fir N.15°W., 10.7 ft. mkd. "T30S R6W S34 CSBT"
- 14" D.Fir S.25°W., 40.5 ft. mkd. "T31S R6W S3 CS BT"

Doug. County Surveyors Office - Gregory Quibell, Deputy -  
Debbie Stewart - April 23, 1981 - C.S. File 61/19-47

-----

Found - 1969 DCSO brass cap, properly marked.

- 22" now 23" Oak S.36°30'E., 70.0 ft. with visible "31S R6W S2 CS BT" showing in rotted face. This tree has been cut into in a search for old scribing & will probably not live.
- 7" now 12" Cedar with well healed double blaze bears N.81°W., 37.6 ft.
- 23" now 25" Fir with "30 S R6W S34 CS BT" visible in partially healed blaze bears N.15°W., 10.7 ft.
- 14" now 16" Fir with "31S 6W S3 CS" visible in partially healed blaze bears S.25°W., 40.5 ft.

New BT - 9" Fir bears S.11½°E., 33.8 ft. scribed "T31S R6W S2 CS BT" in a double blaze.

Fd. OK, Feb. 1994, MLP 1994-0012  
 Fd. Ok by R. Brown, April 1995 - M 119-61  
 Fd. OK by R. Dodge, Jan. 1997 - 1997-0020  
 Fd. Ok by R. Brown, 9/1998 - M129-13  
 Fd. by R. Brown, 6/2011 - 2011-0035  
 Fd. BC 4/2013 - D. Edwards, M165-32

cont.

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION Sec Cor for 34 & 35; 3 & 2, T31-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2891, surveyed Oct 2017/March 2018- (DCSO records Vol. 59 Page 23798-9 & Plat T31-6 2020-1)

-----  
The cor. of secs. 2, 3, 34, & 35, on the N. bdy. of the Tp., reestablished by proportionate measurement by Byron, in 1969; perpetuated by Douglas County Surveyor's Office, in 1981. There is no remaining evidence of the original cor. therefore this point is accepted as a careful and faithful reestablishment of the cor.; monumented with an iron post, 1¼" dia., firmly set, projecting 16 ins. above ground, with a brass cap (properly) mkd.

from which the remains of the bearing trees mkd by Byron  
An oak, 25" dia., bears S.36½°E 70.0 ft., with no marks visible on partially healed blaze.

A cedar, 25" dia., bears N.81¼°W., 37.0 It, with a healed blaze.

A decayed fir stump, 33" dia., bears N.16¾°W., 10.7 ft., no marks visible.

and a BT mkd. by Douglas County Surveyor's Office

A fir, 25" dia., bears S.11¾°E., 33.9 ft., with a healed blaze.

and new bearing trees

A fir, 15" dia., bears N.73°E., 17..9 ft., mkd. T30S R6W S35 BT

A fir, 10" dia., bears S.61°W., 30.5 ft., mkd. T31S R6W S3 BT.

NAD 1983 (2011)

Latitude 42°54'45.06"N. Longitude 123°23'12.83"W.