

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 35, 36, 25 & 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Under Contract #56, dated March 1855 (DCSO records Vol. 17 Page 7197)

Set post, cor. to secs. 35, 36, 25 and 26, from which
A B.Oak 34" dia., bears N.89°W., 27 lks. dist.
A W.Oak 14" dia., bears S.58°W., 49 lks. dist.
A B.Oak 15" dia., bears S.42°E., 89 lks. dist.
A B.Oak 5" dia., bears N.11°E., 127 lks. dist.

J.H. Markham for Stomar Lbr. - Oct. 20, 1949 - C.S. 40/188-3

Determine from O.B.T.'s
Oak stump bears N.89°W., 17.8 ft. scribe legible.
B.Oak S.42°E., 58 ft. rescribe S36, 2880 BT.
W.Oak S.58°W., 49 lks. with scar.
At corner point found 2 wooden stakes, from which
12" Laurel bears N.23°E., 85 ft. mkd. S25 2880 BT.
12" Fir bears N.24°W., 45 ft. mkd. S26, 2880 BT.
7" Laurel bears S.64°W., 9.5 ft. mkd. S35, 2880 BT.
This corner being centered perfectly on top of main ridge.
There is a fence running N & S from cor., the gate being 60 ft. North of cor.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Milo Godfrey - Clete Putnam - July 8, 1960 - C.S. File 52/25-5

Found - 3 original BTs and all four of Markham's.
Also N-S fence 2 ft. East of corner.
Orig. NW BT, now rotted stump, but shows good reverse scribing "BT".
Orig. SW BT, now 24" W.Oak, center rotted.
Orig. SE BT, shows good scar.
Markham's BTs are bark scribed and his NW BT now low cut fir stump.
Set brass cap at corner mkd: County Surveyors S26|S25
Office 1960 S35|S36 T30SR6W
New BTs -Rescribe, now 8" Laurel S.70°W., 9.5 ft. "T30S R6W S35 CS BT."
28" B.Oak S.42°E., 58.7 ft. (orig.) scribed "T30S R6W S36 CS BT."
9" W.Oak N.52°W., 57.5 ft. scribed T30S R6W S26 CS BT.
10" W.Oak N.3°E., 40.5 ft. scribed T30S R6W S25 CS BT.

continued next page

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 35, 36, 25 & 26

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Bruce Shaner - For: Roseburg Resources Co. - June 2002 - M137-44 & C.S. File 65/44-6 J

Found - 1" iron pipe with 2½" brass cap, properly mkd., from which a:
10" Madrone, scribes visible, bears S.70°W., 9.0 ft.
38" B.Oak, face overgrown, bears S.42°E., 58.7 ft.
9" W.Oak bearing N.52°W., 57.5 ft. is now gone.
18" W.Oak stump bears N.3°E., 40.5 ft.
N-S fence is East, 2.0 ft. from corner.
3"x96" alum. pipe is alongside corner.
New BTs- 12" Madrone, scribed "T30S R6W S25 BT" bears N.14°E., 7.1 ft.
8" Madrone, scribed "T30S R6W S26 BT" bears N.15°W., 16.5 ft.
Note - Corner lies on ridge top at 25 ft. west of dirt road running N-S.

Fd. ok by Herm Pieske, 6/2007 - 2007-0088

Carl Sweeden - For: Mike Swett - 3/2015 - M169-11 & M169-75

Found - Corner pipe and cap are gone
Set temp point using BTs as follows:
11" Madrone BT, S.70°W., 9.0' open face, tag
38" B.Oak BT, S.42°E., 58.7', scar, tag, cut off at +/- 7.0'
9" W.Oak BT, N.52°W., 57.5' now gone
18" W.Oak stump, N.3°E., 40.5', 1.0' tall
13" Madrone BT, N.14°E., 7.1', faint bark scribe vis.
8" Madrone BT, N.15°W. 16.5', faint bark scribe vis.