

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 700140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 36; & 31 of T30-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 17 Page 7131)

-----  
Set ¼ sec. post, from which  
A B.Oak 10" dia., bears N.85°E., 13 lks. dist.  
A B.Oak 8" dia., bears S.20°W., 28 lks. dist.

(Flint in an 1855 dependent resurvey, did not establish a new corner. DCSO records, Vol. 17 Page 7195)

George Wenderoth, for: Pfaff and Austin - March 1946 -  
M 20-24 - C.S. File 39/118

-----  
Find old BT one down & both badly rotted (orig. info. added  
Set 3/4" Iron pipe. 9/28/2004 RWS)  
Mark: 14" B.Oak N.53°00'E., 54.4 ft.  
36" B.Oak S.49°05'W., 38.8 ft.

Doug. County Surveyors Office - James Byron, Deputy - Mike  
Darby; Jim Halterman - Nov. 1963 - C.S. File 53/26-30

-----  
Found - 3/4" I.P. at corner.  
18" B.Oak N.53°E., 54.4 ft. shows good scribing.  
SW BT, now snag, shows scribing.  
New BT - 16" R.Fir bears S.8°W., 10.4 ft. scribed ¼ S36 CSBT

Doug. County Surveyors Office - Gary Langlitz; Ed Monrean;  
Karen Reed; P. Earle; F. Silagy; S. Flause - June 13, 1979  
C.S. File 61/3; RM 3-26

-----  
Found - 3/4" I.P. set by Wenderoth. We find this corner to  
have been set by improper procedure. See  
narrative in C.S. File 39/118.  
Did not find original post.  
Original BTs not found.  
14" B.Oak now 18" bears N.53°E., 54.8 ft. (Rec. 54.4  
ft.) with well healed blaze. We open to find a  
visible "¼" scribe.  
36" B.Oak now a 40" dia. stump, bears S.49°W., 38.8  
ft. to face and 40.5 ft. dist. to center.  
16" R.Fir now a 19" dia. snag bears S.8°W., 10.4 ft.  
with a healed over double blaze. We open to find  
visible "¼ S36 CS BT" scribing.

WE DESTROY ALL SCRIBING.

Set a 1" x 36" I.P. with brass cap mkd: "Douglas County  
Surveyor" T30S R6W ¼ S36 S31 R5W 1979, at proper single  
proportioned distance determined by our 1979 survey.

(Cont. Next Page)

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 700140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 36; & 31, T30-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Corner falls on moderate southeast slope. Wenderoth's 3/4" Iron pipe bears S.38°31'27"W., 25.08 ft. from brass cap.  
New BTs -10" D.Fir scribed "¼ S36 CS BT" in double blaze bears N.65°W., 25.9 ft. dist.  
9" D.Fir scribed "¼ S36 CS BT" in a double blaze bears S.52°W., 64.4 t.  
9" D.Fir scribed "¼ S31 CS BT" in a double blaze bears S.84°E., 33.9 ft.  
10" D.Fir bears N.52°E., 39.4 ft. dist., scribed "¼ S31 CS BT" in a double blaze.

Fd. OK, Donald Bentz, March 1986, M 101-1

9/28/2004 Research of this corner by Randy Smith, Deputy Co. Surveyor, showed that in C.S. 39/118 a part of the corner report by George Wenderoth was left off and was added at this time. (Find old BT one down & both badly rotted)

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 10/17/2006 - C.S. File 67/14-33

-----  
Found - 3/4" I.D. iron pipe projects 28" above ground (Wenderoth 1946)  
2½" dia., B.Cap on 1" iron pipe projects 6" above ground. (DCSO 1979) it has been determined by evidence previously omitted from corner renewals notes that Wenderoth established his position from orig. BTs. Therefore we accept this position & cut off the 1979 brass cap leaving the 1" I.P projecting 4" above ground.

**Accessories for 1979 BC/IP**

- 10" now 16" dia., D.Fir, double blazed, bears N.65°W., 26.7' (rec. 25.9')
- 9" now 15" dia., D.Fir snag, double blazed, bears S.52°W., 64.4'
- 9" now 12" dia., D.Fir stump 1 ft. tall, evid. of low blaze, bears S.84°E., 33.9'
- 10" now 15" dia., D.Fir snag, healed double blaze, bears N.52°E., 39.4'

**Accessories for 1946 3/4" IP**

- 19" dia., D.Fir snag, now 18" dia., x 15 ft. tall snag. Shows chopped out blaze bears S.8°W., 10.4 ft. (agrees w/rec.) Used as a fence cor. 1946 BT.
- 18" B.Oak now tipped out & laying on ground, root hole agrees well with rec. (N.53°E., 54.8 ft.) 1946 BT

continued next page

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 700140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 36; & 31 of T30-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Set - Position of  $\frac{3}{4}$ " IP was referenced & removed. Set  $2\frac{1}{2}$ "  
dia., brass cap on  $1\frac{1}{4}$ " O.D. IP at referenced  
position. Reset  $\frac{3}{4}$ " IP at west edge of BC/IP. MKD:  
DOUGLAS COUNTY SURVEYORS OFFICE

T30S

R  $\frac{1}{4}$  R  
6 S 36 | S 31 5  
W 2006 W

BT tags are removed from existing snags. NW BT now  
becomes reference for new position.

- New - 1" I.D. IP, projects 4" above ground bears N.  $36\frac{1}{2}$ °E.,  
25.1 ft. - compass bearing - (Rec. N.  $38^{\circ}31'27''$ E.,  
25.08 ft.) 1979  
17" dia., D.Fir, double blazed & scribed " $\frac{1}{4}$ " S31 CS  
BT" bears N.  $9\frac{1}{2}$ °E., 12.3 ft.  
11" dia., Madrone double blazed & scribed " $\frac{1}{4}$ " S31 CS  
BT" bears S.  $29^{\circ}$ E., 12.7 ft.  
8" dia., W.Oak double blazed & scribed " $\frac{1}{4}$ " S36 CS BT"  
bears S.  $88^{\circ}$ W., 37.2 ft.  
16" dia., D.Fir healed double blazed visible bears  
N.  $16^{\circ}$ W., 32.1 ft. 1979 BT. Now references new  
position.  
Note - Corner bears N.  $8^{\circ}$ E., 10.0 ft. from fence corner  
w/fences extending West & South.  
Compass decl.  $16\frac{1}{2}$ °E.