

PRIMARY CORNER DESCRIPTION CC Tsp cor. S.1 & S.36, T30-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Butler Ives and Geo. Hyde, under Contract #39 dated Jan. 4, 1854 (DCSO records, Vol. 16 Page 6984)

-----  
Set a post, Cor. of Tps. 30 and 31 S., Rs. 4 & 5 W., from which

- A Fir 14" dia., bears N.34°E., 4 lks. dist.
- A Fir 11" dia., bears S.60°E., 17 lks. dist.
- A Laurel 8" dia., bears S.83°W., 33 lks. dist.
- A Live Oak 7" dia., bears N.50°W., 7 lks. dist.

-----  
GLO resurvey by Wm. Thiel under Contract #535 dated Feb. 5, 1889 (DCSO records, Vol. 17 Page 7016)

-----  
The post set for this Cor. is entirely gone, but all the bearing trees are standing. I restore this Cor. by setting a Laurel post, 4½ ft. long 4" sq., 24" in the ground, marked T31S R5W S1 on SW., T30S R5W S36 on NW., faces with 6 notches on N., S., and W. edges, from which

- A Live Oak 8" dia., bears N.50°W., 7 lks. dist., mkd. T30S R5W S36 BT.
- A Laurel 10" dia., bears S.83°W., 33 lks. dist., mkd. T31S R5W S1 BT.

These are the old bearing trees, which I re-mark, as the old marks are overgrown and quite dim.  
This corner stands in a thicket of Laurels, Firs and Live Oaks.

-----  
Doug. County Surveyors Office - April 11, 1957 - C.S. file 47/175

-----  
Found - Remains of old BTs to NE and SE badly rotted but scribe marks plainly visible.  
Clump of Laurel saplings & depression in ground showing location of old tree fit for bearing and distance to laurel bT in SW quadrant.

Set an I.Pipe 1" dia. with brass cap, mkd: County Surveyor's  
T30S R5W | T31S R4W  
36 |  
T31S 1 |  
1957  
Office

from which  
12" Fir S.18°E., 18.9 ft. mkd. T31S R4W S6 CS BT.  
12" Fir N.3°W., 28.2 ft. mkd. T30S R5W S36 CS BT.  
6" Live Oak S.29°W., 33.0 ft. mkd. T31S R5W S1 CS BT.

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 700700

PRIMARY CORNER DESCRIPTION CC Tsp Cor. S.1 & S.36, T30-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by Jelley, Brooks & Roseberry under Group #'s 320 and 614 - Surveyed June 1966/May 1968 (DCSO records, Vol. 35 Page 14355)

-----  
Found 1957 Co. cap with an iron post, firmly set, from which remaining original bearing trees:

A burned fir stump 16" dia., bears N.34°E., 4 lks. dist., with scribe mark T visible on rotted blaze.

A burned fir stump 18" dia., bears S.60°E., 17 lks. dist., with scribe marks R T31S S BT visible in reverse on overgrowth lying on ground.

and bearing trees mkd. by Co. Surveyor in 1957

A Fir 17" dia., bears S.18°E., 28 lks. dist., with a healed blaze.

A live Oak 8" dia., bears S.29°W., 48 lks. dist., with a healed double blaze

A Fir 18" dia., bears N.7°W., 43 lks. dist., with a healed double blaze.

Add marks BLM 1966 to Brass cap.

Corner Fd. OK, BLM survey by Berry and Akin under Group #800 -Surveyed Sept. 1972/June 1973 (DCSO records, Vol. 38 Page 15652)

Fd. Ok by DCSO, Stephen Flauser & John Pike, 4/7/2004 C.S. File 67/6-13