

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 100640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 6; & 1 of T30-8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor under contract # 450 dated July 28, 1882 (DCSO records Vol. 17 Page(s) 7254)

-----  
Set a Fir post 3 ft. long, 3" sq., 18" in the ground for the 1/4 sec. cor. marked 1/4 S. on the W. side and from which  
A Fir 36" dia., bears S.40°E., 8 lks. dist. mkd. 1/4 S BT  
A Chinquapin 8" dia., bears S.35°W., 25 lks. dist. mkd. 1/4 S BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Jim Halterman crew - Feb. 1964 - C.S. File 53/40-38

-----  
Found - Orig. 36" now 56" Fir S.40°E., 5.3 ft. shows good bark scribing "BT".

Orig. SW. BT, not found.

Set Brass cap at cor. mkd: County Surveyors Office

T 30 S

R8W 1/4 S1 | S6 R7W

1964

New BTs -Rescribe now 56" Fir S.40°E., 6.8 ft., bark scribe "1/4 S6 CS BT"

14" W. Fir bears N.53°W., scribed "1/4 S1 CS BT"

Corner about 75 ft. North of small stream and 30 ft. West of logging road.

BLM resurvey by Wayne L. Rogers; Dale T. Bedell; Boyd W. Peterson, Cadastral Surveyors - under Group #1456, surveyed Sept. 1988/Feb. 1989 - (DCSO records Vol. 50 Page(s) 19041-42)

-----  
The 1/4 sec. cor. of secs. 1 and 6, perpetuated and recorded by Byron, Deputy County Surveyor, in 1964, monumented with an iron post, 1 1/4 ins. diam., firmly set, projecting 14 ins. above ground, with 1964 brass cap.

from which the only remaining original bearing tree

A fir, 54 ins. diam., bears S. 40° E., 8 lks. dist., with scribe marks 1/4 S6 CS BT visible on the bark, as remarked by Byron.

and the remains of a bearing tree mkd. by Byron

A sawed fir stump, 15" diam., bears N. 53° W., 30 lks. dist., no visible marks.

and a new bearing tree

A fir, 4 ins. diam., bears N. 80° W., 5 lks. dist., mkd. 1/4 S1 BT.

continued next page

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 100640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 6; & 1 of T30-8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Mark Smalley - For: Roseburg Resources - 9/11/2006 - C.S.  
File 65/58-23

-----

Found - 1964 DCSO IPBC (properly Mkd)  
56" Fir S.40°E., 5.3 poor condition - bark scribe.  
11" Fir N.80°W., 3.3 poor condition - bark scribe.  
New - Scribed 9" Fir N.68°W., 21.5' scribed "¼ S BT"  
Scribed 10" Fir N.18°E., 23.0' scribed "¼ S BT"  
Compass decl. 16½°E.