

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 140300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 450 dated July 28, 1882 (DCSO records Vol. 17 Page(s) 7278)

Set a Fir post 3 ft. long, 3" sq., 18" in the ground for ¼ sec. cor. marked ¼ S on N. face, from which

A Fir 28" dia., bears S.18°E., 54 lks. dist. mkd. ¼ S BT.

A Fir 26" dia., bears N.5°E., 18 lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Jim Halterman crew - Feb. 1964 - C.S. File 53/40-45

Found - Orig. 36" now 38" Fir snag, S.18°E., 35.6 ft., shows good scribing.

Orig. NE. BT, now down, no scribing found.

Set Brass cap at cor. mkd: County Surveyors Office

T 30 S R 7 W

¼ S 19

S 30

1964

No trees near.

We mark sandstone boulder 5'x4'x3' high. We chisel 2" + on pointed top, and B.O. on South face. + on top bears S.14°W., 13.6 ft. from ¼ corner.

Corner is on steep East slope and about 150 ft. East of logging road.

BLM resurvey by Stephen D. Albright and Jack W. Bowder, Cadastral Surveyors, under Group #787, surveyed July/Aug. 1972 - (DCSO records Vol. 36 Page(s) 14889-90)

The ¼ sec. cor., perpetuated and recorded by Byron in 1964, monumented with an iron post, 1½" dia., firmly set, protruding 12" above the ground, with brass cap mkd. in 1964. from which the remains of the original bearing trees:

A root hole bears N.5°E., 18 lks. dist. alongside of which a fallen Fir, size indeterminate, no marks visible.

A Fir snag 40" dia., bears S.18°E., 54 lks. dist., with scribe marks ¼ S visible on bark blaze.

and a bearing object mkd. by Byron in 1964:

A stone 5 x 4 x 3 ft., bears S.14°W., 20½ lks. dist., mkd.

X on top and BO on S. face.

from which new bearing trees:

A Fir 5" dia., bears S.15¼°W., 37 lks. dist. mkd. X BT.

A Fir 6" dia., bears N.11°W., 49 lks. dist. mkd. ¼ S19 BT.