

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 176100

PRIMARY CORNER DESCRIPTION C C for Secs. 5 & 6 only, T31-7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gerald A. Sorrels, U.S. Surveyor, under Group #36, surveyed March/April 1918 - (DCSO records Vol. 19 Page(s) 8094) and duplicated info. in Vol. 27 Pg. 11639)

Intersect the S. bdy. of Sec. 31, T30S R7W, 1.56 chs. S.89°58'W. of the old cor. of secs. 5 and 6 (changed to an angle point.)

At the point of intersection

Set an iron post, 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 5 and 6, with brass cap mkd.

S 6	S 5
T 31 S	R 7 W
1918	

from which

A Fir 14" dia., bears S.62°45'E., 101 lks. dist. mkd. T31S R7W S5 BT.

A B.Oak 6" dia., bears S.21°15'W., 44 lks. dist. mkd. T31S R7W S6 BT.

Douglas Co. Surveyors Office - Vernon R. Tracy; Mike Darby, crew - May/June 1965 - C.S. File 53/40-74

Found - 1918 GLO brass cap

Orig. 14" now 18" Fir S.62°45'E., 66.7 ft., shows very good scar. Tree alive and good condition.

Orig. 6" now 8" B.Oak S.21°15'W., 29.0 ft., shows good scar, top broken out, tree appears to be dying.

New BT - 16" D.Fir S.49°W., 7.4 ft. mkd. T31S R7W S6 CSBT. This corner lies on ridge top. SE. BT is on edge of bluffs, running NE. and SW. also approx. 103 ft. W. of "AP" corner.