

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 31 & 32 only (South)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gerald A. Sorrels, U.S. Surveyor, under Group #36, surveyed March/April 1918 - (DCSO records Vol. 17 Page(s) 7295) and duplicated info. in Vol. 27 Pg. 11617)

A point south of the ¼ cor. bet. secs. 31 and 32
Set an iron post 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 31 and 32, with brass cap mkd.

T30S	R7W
S31	S32
1918	

from which
A Live Oak 12" dia., bears N.32°E., 34 lks. dist. mkd. T30S R7W S32 BT.
A Fir 12" dia., bears N.70°W., 12 lks. dist. mkd. T30S R7W S31 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Mike Darby, crew - May/June 1965 - C.S. File 53/40-77

Found - 1918 GLO brass cap.
Orig. 12" now 14" Live Oak N.32°E., 22.4 ft., scar is unhealed, center rotted out.
Orig. 12" now 26" Fir N.70°W., 7.9 ft., show very good scar, alive and in good condition.
New BT - 26" D.Fir N.48°E., 38.1 ft. mkd. T30S R7W S32 CSBT.
This corner lies on very steep E. slope broken with bluffs and rock outcrops, approx. W. of creek, flowing South.