

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 238100

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 5 only, T31-7

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 17 Page(s) 7231)

-----  
(On offset line, 10.0 chs. South)  
Set ¼ sec. post, no witness trees. Made stone mound.

GLO survey by Gerald A. Sorrels, U.S. Surveyor, under Group #36, surveyed March/April 1918 - (DCSO records Vol. 17 Page(s) 7295) and duplicated info. in Vol. 27 Pg. 11617)

-----  
Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for ¼ sec. cor. of sec. 5 only, with brass cap mkd.

¼ S 5  
1918

from which

A B.Oak 7" dia., bears S.38°E., 9 lks. dist. mkd. ¼ S5 BT  
A B.Oak 24" dia., bears S.66°W., 40 lks. dist. mkd. ¼ S5 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy; Mike Darby; Terry Connell, crew - July 1965 - C.S. File 53/40-79

-----  
Found - 1918 GLO brass cap.  
Orig. 7" now 9" B.Oak S.38°E., 5.9 ft., open and find "S" scribe. Tree is dying.  
Orig. 24" now 24" B.Oak S.66°W., 26.4 ft., dying, shows scar.  
New BTs -12" D.Fir S.24°E., 20.6 ft. mkd. ¼ S5 CS BT.  
13" B.Oak S.5°W., 26.2 ft. mkd. ¼ S5 CS BT.  
This corner lies 162.4 ft. W. of So. 1/4 cor. Sec. 32, T30-7

Survey by Howard Johnstone, LS #498 - For: Roseburg Lumber Co. - Sept. 24, 1984 - M 97-50

-----  
Found - 1918 GLO brass cap and iron pipe.  
26" Oak S.66°W., 26.4 ft., face scar.  
14" Oak S.5°W., 26.2 ft., broken stump.  
10" Oak S.38°E., 5.9 ft., down.  
16" Fir S.24°E., 20.6 ft., down.  
No good trees to the South.  
New BT - 8" Fir N.38°E., 14.7 ft.