

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 33 and 34

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 17 Page(s) 7244)

-----  
Set ¼ sec. post, from which  
A Laurel 7" dia., bears N.12°E., 13 lks. dist.  
A Laurel 8" dia., bears S.30°W., 31 lks. dist.

GLO survey by Gerald A. Sorrels, U.S. Surveyor, under Group #36, surveyed March/April 1918 - (DCSO records Vol. 17 Page(s) 7298) and duplicated info. in Vol. 27 Pgs. 11619-20)

-----  
¼ sec. cor. located by reference to the bearing trees. At the exact cor. point, Set an iron post, 3 ft. long, 1" dia., 26" in the ground for ¼ sec. cor. with brass cap mkd:

¼  
S33 | S34  
1918

from which  
A Madrona 14" dia., bears N.22°E., 13 lks. dist. mkd. ¼ S34 BT. (Old BT).  
A Madrona 12" dia., bears S.30°W., 29 lks. dist. mkd. ¼ S33 BT. (Old BT).  
A Fir 14" dia., bears S.16°30'E., 59 lks. dist. mkd. ¼ S34 BT. (New BT).  
A Fir 18" dia., bears N.34°W., 29 lks. dist. mkd. ¼ S33 BT. (New BT).

Douglas Co. Surveyors Office - James W. Byron, Deputy - Tracy, Heritage and Powell, crew - March 16, 1965 - C.S. File 53/40-98

-----  
Found OK. 1918 GLO brass cap and BTs in good condition. These BTs were tagged by me March 16, 1965.

Fd. OK, March 1994 by R. Quimby - M 119-21

Mark Smalley - For: Roseburg Resources Co. - January 2000 - M 134-7

-----  
Found - 1918 GLO brass cap on iron pipe.  
20" Fir S.16½°E., 38.9 ft. healed.  
32" Fir N.34°W., 19.1 ft. healed.  
15" Madrone S.30°W., 19.1 ft. healed orig.  
18" Madrone stump N.22°E., 8.6 ft. orig.  
Scribed- 8" Fir S.64°W., 26.4 ft. "¼ S BT"