

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 28

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 17 Page(s) 7245)

-----  
Set ¼ sec. post, from which  
A Fir 6" dia., bears S.50°E., 24 lks. dist.  
A Fir 30" dia., bears S.50°W., 51 lks. dist.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, M. Darby;  
J. Barnett, crew - April/May 1965 - C.S. File 53/40-66

-----  
Found - Orig. 6" now 11" Fir, S.50°E., 15.8 ft., open and shows "¼" scribe, tree now snag, approx. 8.0 ft. high.  
Orig. 30" now 38" Fir S.50°W., 33.7 ft., open and shows "¼S" scribe, tree alive.

Set Brass cap at cor. mkd: County Surveyors Office  
T 30 S R 7 W  
¼ S 28 | S 27  
1965

New BTs -14" D.Fir S.83°W., 30.8 ft. mkd. ¼ S28 CS BT.  
8" D.Fir S.4°E., 27.8 ft. mkd. ¼ S27 CS BT.

This corner lies on steep SE. slope approx. 160.0 ft. North of creek.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #571, surveyed May/June 1965 - (DCSO records Vol. 33 Page(s) 13863)

-----  
The ¼ sec. cor., perpetuated by the DCSO in 1965, monumented with an iron post, 1" dia., firmly set, extending 12" above the ground with correctly mkd. brass cap from which the original bearing trees:

A Fir snag 11" dia., bears S.50°E., 21½ lks. dist., with scribe marks ¼ visible on opened blaze. (Rec. 24 lks.)  
A Fir 38" dia., bears S.47°W., 51 lks. dist. with scribe marks ¼ S visible on opened blaze. (Rec. S.50°W.)

and County surveyor's bearing trees:

A Fir 8" dia., bears S.4°E., 42½ lks. dist. mkd. ¼ S27 CS BT on double blaze.  
A Fir 14" dia., bears S.83°W., 45½ lks. dist. mkd. ¼ S28 CS BT on double blaze.

Add marks BLM 1965 to brass cap.

BLM resurvey by Dale T. Bedell, Cadastral Surveyor, under Group #1350, surveyed April/May 1987 - (DCSO records Vol. 48 Page(s) 16800-01)

-----  
(Cont. Next Page)

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 28

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

The ¼ sec. cor., monumented with an iron post, 1¼" dia., firmly set, projecting 12" above ground, with brass cap mkd. by Douglas County and remarked 1965 by BLM from which a bearing tree mkd. by Byron in 1965

A Fir 9" dia., bears S.4°E., 42½ lks. dist. with healed blaze.

and a new bearing tree

A sawed Fir stump 23" dia., bears S.22°W., 50½ lks. dist. mkd. ¼ S28 BT.

**Mark Smalley, Roseburg Forest Products - 9/12/2002 - C.S. File 65/44-18**

Found - 1965 DCSO IPBC - not readable. Monument was buried under about 2 ft. of fill from road above. I had to use a metal detector to find it & dug it out. I was unable to read the cap because of the caked on dirt-clay, etc.

10" Fir stump S.4°E., 27.6 ft.

23" Fir stump S.22°W., 33.3 ft.

New - 4" Fir N.68°W., 13.0 ft., not scribed - tag only.

2½" Fir S.46°E., 30.8 ft., not scribed - tag only.

7" Fir N.26°E., 28.0 ft., scribed "¼ BT"