

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 17 Page(s) 7245)

Set ¼ sec. post, from which
A Pine 40" dia., bears S.30°W., 5 lks. dist.
A W.Oak 10" dia., bears N.80°W., 74 lks. dist.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Mike Darby, Jack Barnett, crew - March 1965 - C.S. File 53/40-65

Found - Stump of orig. BT, very badly rotted, 40" Pine, S.30°W., 3.3 ft., face with "¼S" scribe and old axe marks.

10" Oak BT is gone. (Find an Oak downhill with center rotted away, but no scribe)

Set Brass cap at cor. mkd: County Surveyors Office
T 30 S R 7 W

¼ S 22
S 27
1965

New BTs -10" D.Fir S.43°E., 6.0 ft. mkd. ¼ S27 CS BT.
15" D.Fir N.46°W., 15.8 ft. mkd. ¼ S22 CS BT.

This corner is approx. 300 ft. West of ridge top.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #571, surveyed May/June 1965 - (DCSO records Vol. 33 Page(s) 13864)

The ¼ sec. cor., perpetuated by the County in 1965, monumented with an iron post, 1" dia., firmly set, extending 8" above the ground, with properly mkd. brass cap.

from which the remaining original bearing tree:

A rotted and burned Pine stump, 40" dia., bears S.30°W., 5 lks. dist., with scribe marks ¼ S visible on section of rotted blaze.

and County Surveyor's bearing trees:

A Fir 15" dia., bears N.46°W., 24 lks. dist., mkd. ¼ S22 CS BT on double blaze.

A Fir 10" dia., bears S.39°E., 9 lks. dist. mkd. ¼ S27 CS BT on double blaze.

Add marks BLM 1965 to brass cap.

Fd. OK, July 24, 1973 by M. Smalley - C.S. File 63/153-9

(Cont. Next Page)

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by James E. Jelley, Cadastral Surveyor, Group #1007, surveyed Aug. 1980/March 1982 - (DCSO records Vol. 43 Page(s) 16798)

The ¼ sec. cor., perpetuated and recorded by the County in 1964, monumented with an iron post, 1¼" dia., firmly set, projecting 6" above ground with properly mkd. brass cap. from which the remains of an original bearing tree:

A root crown bears S.30°W., 5 lks. dit. with the remains of a Pine stump in center, no marks remaining.

and bearing trees mkd. by Tracy:

A Fir 17" dia., bears N.45½°W., 24 lks. dist. with healed blaze.

A Fir 13" dia., bears S.41¼°E., 9 lks. dist. with healed blaze.

From this point United States Coast and Geodetic Survey triangulation station "BUCK MOUNTAIN" bears N.11°22'W., 181.14 chs. dist., monumented with a brass tablet 3½" dia., cemented in drill hole in bedrock, mkd. BUCK MOUNTAIN 1942 and a triangle.