

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 17 Page(s) 7240)

Set ¼ sec. post, from which
A Fir 8" dia., bears N.60°E., 64 lks. dist.
A Pine 48" dia., bears S.70°W., 32 lks. dist.

Douglas County Surveyors Office - James W. Byron, Surveyor Tracy, Darby and Barnett, crew - C.S. File 53/40-64 - March 1965

Corner searched for, not found.

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #1007, surveyed Aug. 1980/March 1982 - (DCSO records Vol. 43 Page(s) 16794)

The 1/4 sec. cor., determined at record bearing and distance from the remains of the original bearing trees:
A root crown bears N.60°E., 64 lks. dist. with a down Fir alongside 16" dia., with scribe marks ¼ S visible on opened blaze.
A Pine root crown 25" dia., bears S.70°W., 32 lks. dist. no marks visible.

At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:
T 30 S R 7 W
1/4 $\frac{S\ 23}{S\ 26}$
1982

from which new bearing trees:
A Fir 8" dia., bears N.45°E., 90 lks. dist. mkd. ¼ S23 BT.
A Cedar 6" dia., bears S.66¼°W., 27 lks. dist. mkd. ¼ S26 BT.