

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #350;680, surveyed April/Sept. 1969 - (DCSO records Vol. 35 Page(s) 14499)

-----

Point for the W 1/16 sec. cor. of secs. 1 & 36.  
 Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked: W 1/16  $\frac{S\ 36}{S\ 1}$   
 1969

from which a BT & reference monument  
 A Fir, 5" dia., bears N.66°W., 55½ lks., mkd: 1/16 S36 BT.  
 An iron post, 28" long, 2½" dia., set 24" in the ground, for a reference monument, bears S.48°E., 59½ lks., with brass cap mkd: W 1/16 S1 RM 1969 and an arrow pointing to the corner.

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #680, surveyed June 1977 - (DCSO records Vol. 41 Page(s) 16258)

-----

Point for the W 1/16 sec. cor. of secs. 1 & 36 erroneously established by Jelley in 1969, bears N.71°02'W., 0.17 chs., set, mkd. & witnessed as described in the official rec.  
 I remove the iron post, destroy the marks on the bearing tree, and at the corner point.  
 Reset the iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked: W 1/16  $\frac{S\ 36}{S\ 1}$   
 1977  
 1969 from which

An iron post, 28" long, 2½" dia., set 24" in the ground, for reference monument, bears N.71½°W., 55 lks., with brass cap mkd: W 1/16 S36 RM 1977 and an arrow pointing to the corner.

An iron post, 28" long, 2½" dia., set 24" in the ground, for a reference monument, bears S.39 3/4°E., 43½ lks., with brass cap mkd: W 1/16 S1 RM 1969 and an arrow pointing to the corner.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 9/20/1999 - C.S. File 66/12-28

-----

Found - 2½" dia., BLM brass cap on a 2½" O.D. iron pipe, flush with ground, brass cap marred and unreadable. 1977 BLM  
 3½ dia., BLM brass cap on a 2½" O.D. iron pipe protrudes 2" above ground, bears N.71½°W., 36.3 ft. (agrees w/rec.) 1977 continued next page

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 620100

PRIMARY CORNER DESCRIPTION W 1/16 Sec 36, & S 1 T31-7

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

1977 SE ref. monument now gone.  
New B0s- 17" D.Fir double blazed & scribed "W 1/16 S36 CS BT"  
bears N.8°E., 32.9 ft.  
½" I.R. with yellow BLM plastic cap mkd: BLM" bears  
N.74½°E., 217.5 ft.  
Note - Corner lies 6 ft. northerly of northerly rail of R/R  
tracks. See sketch in file.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and  
Jeff Lorsung - 4/1/25 - C.S. File 67/60-15  
-----  
Found - ¾" BLM brass cap unreadable. Leans slightly  
north, flush.  
¾" BLM brass cap N.67½°W. (Rec N.71°W.) 36.3 ft  
flush. This monument is approx. 1½ ft S.S.W. of  
a 16" Ponderosa Pine.  
24" D. Fir N.9½°E. 32.5 ft (Rec N.8°E. 32.9 ft.)  
Fully healed double blaze. Add ¾" mag nail  
left side center.  
½" Iron rod with yellow BLM plastic cap mkd BLM  
N.77°E. 217.5 ft (Rec N.74½°E.)  
Corner is 6 ft northerly of northerly rail of R/R  
tracks.  
Bearings are local magnetic measured from corner R/R  
rail likely influence compass.  
New - ⅝"x30" Iron rod south 30.0 ft with yellow DCS0  
plastic cap projecting 6".  
Comments - Monument condition is not improved area. Is  
regularly disturbed by railroad maintenance.  
Compass decl. 14¼°E.  
OGRS COORDINATE SYSTEM  
COTTAGE GROVE-CANYONVILLE ZONE  
N - 29312.967 E - 124301.627