



PRIMARY CORNER DESCRIPTION Cor Secs 27, 28, 33 & 34

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Set - Bridge spike in 48" Fir stump. Spike bears S.60½°E., 42.1 ft. Spike stamped "S34"  
Bridge spike in A 38" Fir stump. Spike bears N.77°E., 50.1 ft. stamped "S27"  
Bridge spike in a 30" Fir stump. Spike bears N.74°W., 9.2 ft. stamped "S28"

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2192, Surveyed June/July 2008 - (DCS0 records Vol. 56 Page(s) 22156-7)

-----  
The cor. of secs. 27, 28, 33, and 34, monumented with an iron post, 1¼" dia., firmly set, projecting 4" above the ground, with brass cap (properly) mkd. from which the remains of the original bearing trees  
A roothole bears N.41°E., 4.6 ft., alongside of which is an uprooted, sawed fir stump, 30" dia., with no marks visible.  
A decayed fir snag, size indeterminate, bears S.6°W., 13.2 ft. with no marks visible.  
A roothole bears N.40°W., 31.0 ft., alongside of which is an uprooted, sawed fir stump, 48 ins. diam., with no marks visible.  
and the remains of a bearing tree mkd. by Byron  
A decayed fir stump, size indeterminate, bears N.46¾°E., 70.6 ft., with no marks visible.  
and a bearing tree and an accessory mkd. by Monrean  
A fir, 19" dia., bears S.8¼°W., 30.7 ft., with a healed blaze.  
A sawed fir stump, 31" dia., bears N.74¾°W., 9.2 ft., with a healed blaze and a steel spike driven into the top.  
and bearing trees mkd. by Skeesick  
A fir, 8" dia., bears N.54¾°E., 14.2 ft., with illegible scribe marks visible on a partially healed blaze.  
A fir, 7" dia., bears S.23½°E., 16.6 ft., with illegible scribe marks visible on a partially healed blaze.  
A fir, 6" dia., bears N.51¾°W., 16.0 ft., with illegible scribe marks visible on a partially healed blaze.  
and the remains of accessories mkd. by Monrean, not reported by Skeesick  
A sawed fir stump, 37" dia., bears N.75¼°E., 49.3 ft., with no marks visible and a steel spike driven into the top.  
A sawed pine stump, 49" dia., bears S.62°E., 42.1 ft., with no marks visible and a steel spike driven into the top.

continued next page

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Cor Secs 27, 28, 33 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

The geographic position (NAD 1983 (CORS 96)) of the following corners, as determined in a least squares adjusted network of conventional survey control and GPS occupied points, utilizing dual frequency carrier phase GPS receivers, relative to NSRS CORS "CAPE BLANCO CORS ARP" and National Cooperative CORS Network Station "ROSEBURG COOP CORS ARP", is as follows:

For the corner of sections 27, 28, 33, and 34:  
Latitude: 42°55'31.56"N. Longitude: 123°38'34.71"W.

BLM Dependent resurvey by A Bert Skeesick Cadastral Surveyor, under Group No. 2300: Admin. file #0906, surveyed July 2006/May 2007 - (DCSO recs Vol 56 Pg 22320 & Plat T30-8 2011)

-----  
The cor. of secs. 27, 28, 33 & 34, remonumented by Byron in 1958, perpetuated by Monrean in 1976, monumented with an iron post, 1¼" dia., firmly set, projecting 4" above ground, with brass cap (properly) mkd.

from which the remains of the orig. BTs

A roothole bears N.41°E., 4.6 ft. with an uprooted sawed fir stump, 30" dia., alongside, with no marks visible.

A fir snag, 21" dia., bears S.6°W., 13.2 ft. with no marks visible.

A roothole bears N.40°W., 31.0 ft. with an uprooted sawed fir stump, 48" dia., alongside, with no marks visible.

and the remains fo a BT mkd by Byron

A decayed fir stump, 14" dia., bears N.46¾°E., 70.6 ft. with a healed blaze.

and BTs mkd by Monrean

A fir, 19" dia., S.8¾°W., 30.7 ft. with a healed blaze.

A sawed fir stump, 31" dia., bears N.74¾°W., 9.2 ft. with a healed blaze and steel spike driven into the top.

and new BTs

A fir, 7" dia., bears N.54¾°E., 14.2 ft., mkd: T30S R8W S27 BT.

A fir, 7" dia., bears S.23½°E., 16.6 ft., mkd: T30S R8W S34 BT.

A fir, 6" dia., bears N.51¾°W., 16.0 ft., mkd: T30S R8W S28 BT.

BLM resurvey by George M. Winter, Cadastral Surveyor, under Group No. 2698, surveyed April 2013/Feb. 2014 - (DCSO records Vol. 58 page(s) 23152-3)

-----  
The cor. of secs. 27, 28, 33, and 34, monumented with an iron post, 1¼" dia., firmly set, projecting 3" above ground, with brass cap (properly) mkd.

continued next page

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Cor Secs 27, 28, 33 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of the original bearing trees  
A roothole bears N.41°E., 4.6 ft., alongside of which is an uprooted, sawed fir stump, 30" dia., with no marks visible.  
A decayed fir snag, size indeterminate, bears S.6°W., 13.2 ft., with no marks visible.  
A roothole bears N.40°W., 31.0 ft., alongside of which is an uprooted, sawed fir stump, 48" dia., with no marks visible.  
and the remains of a bt mkd. by Byron, in 1958  
A decayed fir stump, size indeterminate, bears N.46¾°E., 70.6 ft., with no marks visible.  
and remains of accessories mkd. by Monrean, in 1976  
A sawed fir stump, 37" dia., bears N.75¼°E., 49.3 ft., with no marks visible and a steel spike driven into the top.  
A sawed pine stump, 49" dia., bears S.62°E., 42.1 ft., with no marks visible and a steel spike driven into the top.  
A fir, 20" dia., bears S.8¼°W., 30.7 ft., with a healed blaze.  
A sawed fir stump, 31" dia., bears N.74¾°W., 9.2 ft., with a healed blaze and a steel spike driven into the top.  
and bearing trees mkd. by Skeesick in 2006-07  
A fir, 9" dia., bears N.54¾°E., 14.2 ft., with illegible scribe marks visible on a partially healed blaze.  
A fir, 9" dia., bears S.23½°E., 16.6 ft., with illegible scribe marks visible on a partially healed blaze.  
A fir, 7" dia., bears N.51¾°W., 16.0 ft., with illegible scribe marks visible on a partially healed blaze.

NAD83 (CORS 96):

Latitude: 42°55'31.56" N      Longitude: 123°38'34.71" W