

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 17 Page(s) 7327)

 Set a chincapin post 4 ft. long, 4" sq., 24" in the ground for the corner to Secs. 22, 23, 26, & 27, marked T30S R8W S23 on the NE face, S26 on the SE face S27 on the SW face and S22 on the NW faces, with 2 notches on S and E edges, from which
 A fir, 16" dia. bears N.63°E., 37 lks mkd: T30S R8W S23 BT
 A fir, 15" dia. bears S.57°E., 21 lks mkd: T30S R8W S26 BT
 A fir, 5" dia., bears S.61°W., 22 lks mkd: T30S R8W S27 BT
 A fir, 18" dia. bears N.26°W., 25 lks mkd: T30S R8W S22 BT

Douglas Co. Surveyors Office - James W. Byron, Deputy - Milo Godfrey - S.A. Bilow - Sept. 3, 1958 - C.S. File 49/108-6

 Found - Fir Tree, now 33" N.26°W. 16.5 ft. This tree was bark scribed. Could see scribing "S R8W S2 BT". Rescribe this Tree in bark "T30S R8W S22 CS BT"
 Fir Tree, now 21" dia. N.63°E., 24.4 ft. Upper scar has been opened, nearly grown over, but can see portions of scribing. Did not rescribe.
 Fir snag, now 18" dia., S.57°E., 13.9 ft. Upper scar has been opened & scribing "8W S26" is visible.
 Fir, down & dead, 5" dia., S.61°W., 14.5 ft. both scars are open & show almost no growth since being blazed, scribing, "R8W S27 BT" is still visible.
 At corner set iron pipe with brass cap mkd: County Surveyors Office 1958 T30S R8W $\begin{array}{c} S 22 | S 23 \\ S 27 | S 26 \end{array}$
 Blaze & scribe -
 20" D.Fir S.32°E., 40 ft. T30S R8W S26 CS BT.
 18" D.Fir S.57°W., 31.8 ft. T30S R8W S27 CS BT.

Douglas Co. Surveyors Office - Gary Langlitz - M. Lenora Ladig - A. Vic Cangie - Feb. 18, 1976 - C.S. File 59/8-2

 Found - 1" I.P., 12" above ground with 1958 County Brass cap. 1958
 The NE and NW orig. BTs have both blown down, however they appear to have stood in their proper locations.
 An orig. 15" Fir, now 18" snag bears S.57°E., 13.9 ft. with scribing "SW S26 visible on previously opened blaze.
 We find no trace of the orig. SW BT.
 A 20", now 22" D.Fir, alive and well healed, bears S.32°E., 40.0 ft. continued next page

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Cor Secs 22, 23, 26, & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

An 18" D.Fir, now a snag with scribing "T30S R8W S27 CS BT" visible on a double blaze bears S.57°W., 31.8 ft. 1958
New BTs- A 25" D.Fir, bears S.34½°W., 68.5 ft. scribed "T30S R8W S27 CS BT" on a double blaze.
A 7" G.Fir, bears N.42°W., 86.0 ft. scribed "T30S R8W S22 CS BT" on a double blaze.
Note - The area NW of this corner has been clearcut. This cor. is located approx. 100 ft. east of the road 30-8-25 leading to Live Oak Mtn
Com. Dec. setting: 20° east.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2192, Surveyed June/July 2008 - (DCSO records Vol. 56 Page(s) 22154-5)

The cor. of secs. 22, 23, 26, and 27, perpetuated by Byron, in 1958, subsequently perpetuated by the Douglas County Surveyor's Office in 1976, monumented with an iron post, 1¼" dia., firmly set, projecting 9" above the ground, with brass cap (properly) mkd.
from which the remains of the original bearing trees
A roothole bears N.63°E., 24.4 ft., alongside of which is an uprooted, sawed, decayed fir stump, 24" dia., with no marks visible.
A decayed fir snag, size indeterminate, bears S.57°E., 13.9 ft., with no marks visible.
A roothole bears N.26°W., 16.5 ft., alongside of which is an uprooted, sawed fir stump, 32" dia., with a healed blaze.
and the remains of bearing trees mkd. by Byron
A sawed, decayed fir stump, 22" dia., bears S.32¾° E., 40.6 ft., with a healed double blaze.
A decayed fir snag, 19" dia., bears S.58¼°W., 31.7 ft., with scribe marks T30S R8W S27 CS BT visible on open double blaze.
and a BT mkd. by the Douglas County Surveyor's Office
A fir, 28" dia., bears S.34°W., 68.4 ft., with a healed blaze.
and new bearing trees
A fir, 13" dia., bears N.29½°E., 81.7 ft., mkd. T30S R8W S23 BT.
A fir, 8" dia., bears S.77¼°E., 28.1 ft., mkd. T30S R8W S26 BT.
A fir, 10" dia., bears N.39¼°W., 26.3 ft., mkd. T30S R8W S22 BT.
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center. continued next pg

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Cor. Secs. 22, 23, 26, & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Corner is located 130 ft. E. of a dirt road, 9 ft. wide, bears N.25°E. and S.35°W.

The geographic position (NAD 1983 (CORS 96)) of the corner of sections 22, 23, 26, & 27, as determined by direct occupation utilizing dual frequency carrier phase GPS receivers, relative to National Spatial Reference System (NSRS) Continuously Operating Reference Station (CORS) "CAPE BLANCO CORS ARP" and National Cooperative CORS Network Station "ROSEBURG COOP CORS ARP", is as follows:

Latitude: 42°56'25.627"N. Longitude: 123°37'23.911" W.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2972, surveyed May 2020/Feb2021 - (DCSO records Vol. 59 Page(s) 23953-4)

The cor. of secs. 22, 23, 26, and 27, reported by Saveland in June through July of 2008, monumented with an iron post, 1¼" dia., firmly set, projecting 12" above ground, with a brass cap (properly) mkd.

from which the remains of the BTs reported by Saveland

A fir, 17" dia., bears N.29½°E., 81.7 ft., with a healed blaze.

A roothole bears N.63°E., 24.4 ft., alongside of which is a down uprooted, decayed fir stump, size indeterminate, no marks visible. (Original)

A fir, 16" dia., bears S.77¼°E., 28.1 ft., with a healed blaze.

A broken, decayed fir stump, size indeterminate, bears S.57°E., 13.9 ft., no marks visible. (Original)

A decayed fir stump, 26" dia., bears S.32¾°E., 40.6 ft., with a healed double blaze.

A fir, 29" dia., bears S.34°W., 68.4 ft., with a healed blaze.

A decayed fir snag, 18" dia., bears S.58¼°W., 31.7 ft., with scribe marks T30S R8W S27 CS visible on partially healed blaze.

A fir, 14" dia., bears N.39¼°W., 26.3 ft., with a healed blaze.

A roothole bears N.26°W., 16.5 ft., alongside of which is an uprooted, decayed fir stump, 32" dia., with a healed blaze. (Original)