

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 35

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 17 Page(s) 7326-7)

Set a chincapin post 3 ft. long, 3" sq., 18" in the ground, for 1/4 sec. cor., marked 1/4 S on N face; from which
 A fir, 20" dia., bears N.37°W., 21 lks., mkd: 1/4 S BT.
 A fir, 16" dia., bears S.26°E., 11 lks., mkd: 1/4 S BT.

Reported as not fd by V.R. Tracy, 4/1965, C.S. File 53/67-50

Howard W. Johnstone - For: Roseburg Lumber Co. - June 30, 1982 - M 92-52

Found - 36" fir stub with cruiser marks & remnants of tag. Did not find scribing - dirt has been pushed against tree from fire trail through corner. Other BT falls in fire trail, and is gone. Location is consistent with our records of R.H. Gee's 1949 survey when both BTs were found.
Set - 5/8" x 36" I.R. & alum cap S.37°E., 13.9 ft. from fir stub(OBT) (Cap mkd LS 498)
New BTs- 6" fir bears S.34°E., 2.8 ft. (scribed)
 5" fir bears N.17°E., 15.1 ft. (scribed).

Fd. Ok by D. Edwards, 2/2005 - C.S. File 65/55-1. Set 6' post 2' West.

Douglas Co. Surveyors Office - Stephen Flause - John Pike - 2/24/2005 - C.S. File 67/10-8

Found - 5/8" I.R. w/1 1/2" Alum. cap mkd: "T30S R8W 1/4 26/35 1982 LS 498" protruding 7" out of ground. Steel fence post bears West 2 ft. (1982)
 6" now 12" D.Fir healed single blaze visible bears S.34°E., 2.8 ft. (agrees w/rec)
 NE BT now down shows fully healed blaze, root depression measures for brg. & dist.
New - 9" D.Fir, double blaze & scribed "1/4 S35 CS BT" bears S.83°W., 13.3 ft.
 18" D.Fir, double blazed & scribed "1/4 S26 CS BT" bears N.38°W., 26.5 ft.
 14" Grand Fir, double blazed & scribed "1/4 S26 CS BT" bears N.40 1/2°E., 43.0 ft.
Note - Corners lies in old skid rd. just East of shallow draw on Northwesterly slope. Heavily timbered

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 35

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2192, Surveyed June/July 2008 - (DCSO records Vol. 56 Page(s) 22151-2)

The 1/4 sec. cor. of secs. 26 & 35, perpetuated by Johnstone from original evidence no longer in existence, subsequently perpetuated by Douglas County Surveyor's Office in 2007, monumented with an iron rebar, 5/8" dia., firmly set, projecting 8" above the ground, with an aluminum cap (properly) mkd.

from which the remains of bearing trees mkd. by Johnstone

A roothole bears N.17 1/2°E., 14.8 ft., alongside of which is a down fir snag, 13" dia., with a healed blaze.

A fir, 13" dia., bears S.37°E., 3.1 ft., with a healed blaze.

and BTs mkd. by the Douglas County Surveyor's Office

A fir, 15" dia., bears N.39 1/4°E., 43.2 ft., with scribe marks 1/4 S26 BT visible on a partially healed double blaze.

A fir, 10" dia., bears S.77 1/4°W., 13.2 ft., with scribe marks 1/4 S35 BT visible on a partially healed double blaze.

A fir, 19" dia., bears N.39°W., 26.9 ft., with scribe marks 1/4 S26 BT visible on a partially healed double blaze.