

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 17 Page(s) 7328)

A fir tree 12" dia., which I marked 1/4 S on North face for 1/4 sec. cor. from which a
 Fir, 46" dia., bears S.31°E., 5 lks., mkd 1/4 S BT and a
 Fir, 8" dia., bears N.2°W., 34 lks., mkd 1/4 S BT

Clifford M. Bryden - May 7, 1958 - C.S. File 42/357

The 12" dia. Fir scribed 1/4 S on North face for the 1/4 Corner was found but is now a snag.
The 46" dia. Fir BT is a snag & scribe near obliteration due to fire.
The 8" dia. Fir BT is gone.
Using the 12" diam. Fir Snag scribed 1/4 S on North face as corner, I scribe, in the wood, two new BTs as below:
 27" dia. D.Fir that lies N.01°30'E., 49.7 ft. from the Corner, marked 1/4 S BT S23.
 23" dia. D.Fir that lies S.50°00'W. 96.1 ft. from the Corner, marked 1/4 S BT S26.

Howard W. Johnstone - For: Roseburg Lumber Co. - Wit: R. Hendrickson & J. Clark - Sept. 15, 1961 - C.S. File 51/163-5

Set - 1"x30" iron pipe on north side of stump.
Found - 12" Fir with 1/4 S on north face, now a stump.
 27" Fir N.1 1/2°E., 49.7 ft. now a badly burned stump its scribe not discernable, rescribed this stump, 1/4 S BT S23.
 Fir S.50°W., 96.1 ft. is now a stump, scribe in good condition.
Note - This corner falls in the middle of a logging unit and there are no standing trees for new BTs.

Douglas Co. Surveyors Office - Gary Langlitz - Peter Earle - June 26, 1974 - C.S. File 56/51-27

Found - 12" Fir stump with possible scribed area chopped away. Also fd a 1 1/4" I.P. set on northerly edge of stump. 1958, 1961 from which
 52" Fir stump bears S.45°E., 6.0 ft. to center of stump, 3.4 ft. to apparent face of stump. Orig. notes indicate a 46" Fir at record measurement S.31°E., 3.3 ft. This stump badly burnt.
 27" Fir stump bears N.1 1/2°E., 50.6 ft. (Rec. N.1 1/2°E., 49.7 ft.) scribed "1/4 S BT S23"
continued next page

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

20" Fir stump bears S.50°W., 96.1 ft. scribed "¼ S
BT Sec. 26"
Set - We set a steel fencepost with survey marker witness
sign attached alongside corner stump.
There are no trees near.

Tony Hostetter - For: Roseburg Resources - Nov. 2010 - C.S.
File 65/69-61

Found - 1985 BLM brass cap and BTs as described in Vol.47
Page 18107, except fir at S.76½°E., is now a
stump, no tag or marks.
New BT - 18" fir, scribed "S25 ¼ BT", Roseburg tag, bears:
N.52°E., 52.8 ft to spike placed in root collar
below scribing.