

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 100300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19 & 30; 24 & 25, T30-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 17 Page(s) 7379)

Set post cor. secs. 19, 30, 24 and 25, from which
A Fir 20" dia., bears S.40°W., 40 lks. dist.
A Fir 10" dia., bears N.87°W., 45 lks. dist.
A Fir 24" dia., bears N.76°E., 42 lks. dist.
A Hemlock 4" dia., bears S.72°E., 35 lks. dist.

GLO survey by William Bushey, Deputy Surveyor, under Contract #613, dated April 29, 1893 (DCSO records Vol. 17 Page(s) 7406)

(75.85 chs.)
The sec. cor., 6 lks. West of my line. I destroy this post and also the marks on three of the witness trees which I find here.
North, 80.0 chs.)
Set cor. to secs. 19, 24, 25 and 30, West of my line and on the blazed line which cor. is a tone 24x10x8 ins., 18" in the ground mkd. with 2 notches on S. and 4 notches on N. edges, from which
A Fir 34" dia., bears N.27°E., 18½ lks. dist. mkd. T30S R9W S19 BT.
A Fir 30" dia., bears S.51¼°E., 47 lks. dist. mkd. T30S R9W S30 BT.
A Fir 32" dia., bears S.22°W., 33¼ lks. dist. mkd. T30S R10W S25 BT.
A Fir 14" dia., bears N.52½°W., 30 lks. dist. mkd. T30S R10W S24 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - Nov. 1965 - C.S. file 53/53-31

Found - 32" Fir stump S.22°W., 21.8 ft., opened stump, found scribing "R10"
14" Fir, now dead snag, N.52½°W., 19.8 ft., scribed.
34" Fir stump N.27°E., 12.2 ft. (should be 10.2 ft.)
30" Fir stump S.51¼°E., 31.0 ft.

Set Brass cap at cor. mkd: County Surveyors Office

T 30 S
R10W S 24 | S 19 R9W
S 25 | S 30
1965

New BTs- 20" Cedar N.30°E., 24.8 ft."T30S R9W S19 CS BT."
6" D.Fir N.84°E., 46.2 ft. scribed S19 CS BT.

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19 & 30; 24 & 25, T30-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by Mark Smalley - For: Roseburg Forest Products - Feb. 1994 - M 119-18

Found - 1965 DCSO brass cap/iron pipe, out of ground. Reset from bearing trees.
14" Fir N.52½°W., 19.8 ft., snag. Orig. BT.
30" Cedar N.30°E., 24.8 ft., healed face.
12" Fir N.84°E., 46.2 ft., found scribe.
30" Fir S.51¼°E., 31.0 ft., rotten stump. Orig. BT.
32" Fir S.22°W., 22.0 ft., rotted stump. Orig. BT.
34" Fir N.27°E., 12.2 ft., rotten stump. Orig. BT.
Scribed- 12" Fir N.83°W., 8.3 ft. "S24 BT"
8" Cedar S.6°E., 20.1 ft. "S30 BT"
6" Cedar S.6°W., 23.4 ft. "S25 BT"

Coos County Surveyors Office - Michael Dado, Surveyor - Crew: Matthew Martin & Bill Hales - 2/24/2015 - C.S. File 65/87-50

Found - 1965: 2½" brass cap on 1¼" O.D. iron pipe, 1.0' tall, in good condition and solid in the ground. We Set a White Cedar post 2' north and paint the top in blue. Note: there is a D.Fir pistol-butt tree (broken off) 3' north of the BCIP.
1893: 36" D.Fir duff stump, N.25°E., 11.90' to heart center, 10.8' to face. We find visible scribes and an old tag (7-4-41). We paint the scribes in blue. Poor condition.
1893: 30" D.Fir stump, S.24°W., 21.67' to heart center, 20.57' to face. We find visible scribes. We paint the face in blue. Fair condition.
1893: 28" D.Fir stump, S.49°E., 30.26' to heart center. We find visible scribes. We paint the face in blue. Poor condition.
1965: 36" W. Cedar stump, N.31°30'E., 25.59' (24.8' rec.) to heart center. We find an off-set healed blaze. We add a new tag and paint the top of the stump in blue. Good condition.
1965: 17" D.Fir hollow stump, N.85°30'E., 47.34' (N.84°E - 46.2' rec.) to heart center. We find visible scribes. We paint the top of the stump in blue. Good condition.
1994: 11" W. Cedar, S.11°E., 19.84' (S.06°E., 20.1' rec) to right side center. We find visible scribes in a mostly healed blaze and a Roseburg Resources tag in place. We paint the face and a band around the tree in blue. Good Condition.

continued next page

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19 & 30; 24 & 25, T30-10

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

1994: 10" W. Cedar, S.05°W., 23.21' to right side center. We find a healed blaze and a Roseburg Resources tag in place. We paint the blaze and a band around the tree in blue. Good condition.

1994: 16" D.Fir, partly open blaze with a Roseburg (RFP 9-93) tag in place. Tree has been broken off and is tipped-out. We measure N.80°W., 8.2' to a slab still remaining in the ground. We paint the face in blue.

New BT - 4" D.Fir, N.40°W., 23.19' to a nail at right side center. We chop an "X" high and blaze and scribe "BT" low. We paint the blaze, scribes and "X" in blue and attach a yellow Coos Co. tag.
Dec. 17°

ON THE COUNTY LINE - CHECK WITH COOS COUNTY
FOR POSSIBLY MORE INFORMATION