

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 18

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Wm. Bushey, Deputy Surveyor, contract 613, dated April 29, 1893 - (DCSO records Vol. 17 Page(s) 7449)  
-----  
A Fir, tree, 14" dia., which I mark ¼ S on N side for ¼ sec. cor., from which  
    A fir, 30" dia., bears N.15°E., 49½ lks., mkd: ¼ S BT.  
    A fir, 11" dia., bears S.87¾°W., 22¼ lks., mkd: ¼ S BT.

Bruce Shaner - For: Moore Mill & Lumber Co. - M49-54 - Feb. 4, 1974  
-----  
Found - 30" fir stump, orig. BT, old face badly burned bears N.15°E., 32.7 ft.  
        18" fir snag, orig. BT, scribe "T" vis. bears S.87¾°W., 14.7 ft.  
        14" fir, marked as a corner tree, now gone.  
New BTs- 10" cedar, scribed "¼ S7 BT" bears N.22½°W. 18.8 ft.  
        10" D.Fir scribed "¼ S18 BT" bears S.3½°W., 44.2 ft.  
Set - Brass cap mkd: T30S R9W WM ¼S S7, S18 1973.

Fd. BC & 5 BTs, T. Hostetter, 3/2008 - M155-26

BLM retracement by Aaron M Graham, Cadastral Surveyor, under Group No 2164, surveyed June/Oct. 2007 - (DCSO records Vol. 56 Page(s) 22256-8 & BLM Plats 2010-1 & 2010-3)  
-----  
The ¼ sec. cor. of secs. 7 & 18, perpetuated by Shaner, in 1974; monumented with an iron post, 1" dia., firmly set, projecting 6" above ground, with brass cap (properly) mkd. from which the remains of the original BTs  
    A fir stump. 36" dia., bears N.15°E., 32.7 ft., with illegible scribe marks visible on partially healed blaze.  
    A decayed fir stump, size indeterminate, bears S.87¾°W., 14.7 ft., no marks visible.  
and the remains of the BTs mkd. by Shaner  
    A fir, 16" dia., bears S.1½°W., 44.4 ft., with a healed blaze.  
    A cedar stump, 6" dia., bears N.22½°W., 18.8 ft., with scribe marks 4 S7 visible on open blaze.  
and a new bearing tree  
    A fir, 15" dia., bears N.53¾°W., 22.2 ft., mkd. ¼ S7 BT.