

PRIMARY CORNER DESCRIPTION Line Tree between Secs. 19 & 20

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original GLO survey by Wm. Bushey, Deputy Surveyor, under Contract No. 613, dated April 29, 1893 (DCSO records Vol. 18 Page(s) 7443)

-----  
A Fir, 4 ft. dia., on line, marked with 2 notches on N & S sides.

Gary Smither - For: Moore Mill Co. - Jan. 2001 - M136-54

-----  
Found - Orig. line tree, rec. 48" Fir now 46" broken snag 15 ft. high w/2 notches in the bark on the north side - bark has been reduced in size by the fire.

Excerpt from narrative:

Our retracement led us to an orig. 4 ft. dia. Fir line tree 7.79 chains North of the orig. W  $\frac{1}{4}$  corner. This tree had been marked with 2 notches on the North & South sides. We found a 46" dia., 15 ft. tall broken D.Fir snag with 2 notches in the remaining bark on the North side of the tree. This tree has been burnt which thinned the bark (No notches on South side). In 1964 & 1965, when the perimeter of this section was remonumented, the records show that in some cases over the 70 years since the orig. corner was set some of the remaining BTs grew as little as 4 to 6 inches. When we cut into one of the live Firs looking for scribes we found very tight growth rings, indicating slow dia. growth. This evidence supported our acceptance of this line tree & to use it in our proportion of the W  $\frac{1}{4}$ .