

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 300140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 32 & 33

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Wm. Bushey, Deputy Surveyor, contract 613, dated April 29, 1893 - (DCSO records Vol. 17 Page(s) 7422)  
-----  
Set a stone 14x8x8", 9" in the ground for 1/4 sec. cor. mkd. 1/4 on W face, from which  
    A fir, 14" dia., bears N.19 3/4°E., 27 3/4 lks., mkd: 1/4 S BT.  
    A fir, 21" dia., bears N.18°W., 41 lks., mkd: 1/4 S BT.

Douglas Co. Surveyors Office - Gary Langlitz - P. Earle - 4/16/1974 - C.S. File 56/49-11  
-----  
Found - A stone, split, 14"x8"x6", with a "1/4" chiseled on the East face (orig. notes call for stone to be marked on west face)  
        14", now 24" Fir snag, bears N.18°W., 27.1 ft. showing well healed blazed. I do not open.  
        No trace of original NE bearing tree.  
Set - Brass cap at corner point mkd:  
            COUNTY SURVEYORS T 30 S R 9 W  
                    OFFICE S 32 | S 33  
                    1974 1/4  
Reset stone alongside brass cap.  
New BTs- 10" hemlock, bears S.39 1/2°W., 15.6 ft. scribed "1/4 S32 CS BT"  
        8" D.fir, bears S.22°E., 22.2 ft. scribed "1/4 S33 CS BT"  
Steel fence post alongside brass cap  
Magnetic declination 20° east.