

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Wm. Bushey, Deputy Surveyor, contract 613, dated April 29, 1893 - (DCS0 records Vol. 17 Page(s) 7419)

Set a stone 12x12x5", 8" in the ground for 1/4 sec. cor. mkd. 1/4 on N face, from which
 A fir, 5" dia., bears S.48 1/4°E., 15 1/4 lks., mkd: 1/4 S BT.
 A sugar Pine, 5" dia., bears N.76°E., 29 1/4 lks. mkd: 1/4 S BT

Reported as not found - DCS0 11/1965 - C.S. File 53/53-15

Ken Hoffine - For: Lone Rock Timber Co. - Gary Angiolet - 10/19/2012 - C.S. File 65/77-46

Found - Orig. 5 ft sugar pine dead snag no bark on tree bears N.76°E., 19.3 ft. As per rec., healed face
 Orig. 5 ft fir bears broken missing top bears S.48 1/4°E., 10.4 ft. as per record, healed face.
 Orig. 12x12x5" stone with 1/4 scribed on North face.
New - Set 5/8" iron rod with orange plastic cap marked Lone Rock Timber PLS 2291 North 0.25 ft. from center of stone
 Metal fence post approx. North 0.75 ft. from original stone
 13" D.Fir bears S.31°W., 34.1 ft. we scribe 1/4 S27 BT and nail aluminum bearing tree tag to the tree
 21" D.Fir bears S.55°W., 34.0 ft. we scribe 1/4 S27 BT and nail aluminum bearing tree tag to the tree
Note - Fd orig. stone and BTs on steep easterly facing slope. We also looked for orig. line trees called for in GL0 notes on south line of sec. 22 We use a Trimble CE0 6000 to check record bearings and distances.
 We fd the orig. line tree called for at S.89°43'E., 7.83 chs from the 1/4 corner. This tree is now a 27" fir with visible marks from which a BT bears N.42°W., 12.8 ft. with healed face and BLM tag.
 Three orig. line trees clustered N.89°43'W., approx. 1 chain of the 1/4 corner are now blown over and burned but no conclusive line tree evidence.
 Orig. line tree N.89°43'W., 15.1 chs from the 1/4 corner I find two 18" stumps near the record bearing and distance but no conclusive line tree evidence.
 Orig. line tree at N.89°43'W., 36.48 chs from 1/4 corner I find at record bearing and distance very rotten burned stump remains but no conclusive line tree evidence.