

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GL0 survey by Dennis Hathorn, US Deputy Surveyor under contract 57 dated April 12, 1855 - (DCSO Records Vol. 17 Page(s) 7393</p> <p>-----</p> <p>Set ¼ sec. post, from which A fir, 14" dia., bears N.70°E. 33 lks. A fir, 8" dia., bears N.70°W. 7 lks.</p>
<p>Howard W. Johnstone - For: Roseburg Lumber Co. - Oct. 12, 1961 - C.S. File 51/163-9</p> <p>-----</p> <p>Found - 14" Fir N.70°E., 33 lks., (now a 26" high stump) 8" Fir N.70°W., 7 lks. (down, scribe visible) New BTs- 12" Fir S.87°E., 29.5 ft. 8" Cedar N.23°W., 13.0 ft. Set - 1"x30" iron pipe 24" in ground.</p>
<p>Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Mike Darby - July 27, 1964 - C.S. File 53/53-52</p> <p>-----</p> <p>Found - 1"x30" I.Pipe called for in 1961 8" cedar N.23°W., 13.0 ft. 12" Fir is down. New BT- 20" D.Fir S.28°E., 66.6 ft. mkd: ¼ S2 CS BT. Note - This corner lies about 6.0 ft SW of old logging spur</p>
<p>Douglas Co. Surveyors Office - John M. Powell & Crew - 9/27/1967 - C.S. File 53/53-20</p> <p>-----</p> <p>Found - 1" Iron pipe 4' from edge of new road, see 1964 ren. 8" cedar, now uproot, N.23°W., 13.0 ft. 20" D.Fir, now burnt stump, S.28°E., 66.6 ft. scribe visible, "S". Set brass cap at cor. mkd: COUNTY SURVEYORS T30S R9W OFFICE 1967 ¼ S3 S2 New B0s- 30" Fir stump, N.34°W., 29.4 ft. drove iron spike in top of stump. 28" Fir stump, N.7°E., 32.0 ft. drove iron spike in top of stump. Note - This area was recently burned. No tree to scribe. Corner lies on West edge of cat road.</p>
<p>Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - 7/19/1973 - C.S. File 56/34-14</p> <p>-----</p> <p>Found - No trace of IP or brass cap. 1967 30" Fir stump, N.34°W., RR spike driven in top. continued next page</p>

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

28" fir, stump, N.7°E., 32.0 ft. RR spike driven in top.
Set brass cap mkd: COUNTY SURVEYORS T30S R9W
OFFICE ¼ S3|S2
1973
Note - This cor. lies 4.0 ft. west of cat fire road. This area appears to have been burned again.

Shaner Engineering - For: Moore Mill & Lumber - Jan. 12, 1974 - M 49-51

Found - 1973 County Surveyors Brass cap.
30" D.Fir burned stump BT, bears N.34°W., 29.4 ft. RR spike driven into top of stump through burnt BT tag.
28" D.Fir burned stump, bears N.7°E., 32.0 ft. RR spike driven into top of stump through burnt BT tag.
10" D.Fir scribes vis. tree now down, bears S.75°E., 27.0 ft.
New BTs- 10" Cedar, scribed "¼ S2 BT", bears N.40½°E., 87.5 ft.
12" Cedar, scribed "¼ S3 BT" bears N.88½°W., 122.6 ft.

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - Dec. 11, 1989 - C.S. File 64/3-8

Found - A 1973 DCS0 2½" dia. brass cap on a 1 3/8" O.D. iron pipe, leaning 1½ ft. south of plumb.
30" now 18" dia. 2 ft. high burnt and rotted D.Fir stump, no boat spike seen, bears N.34°W., 29.4 ft. 1967
28" now 24" dia. 5 ft. high burnt and rotted D.Fir stump, with boat spike in top near center, boat spike bears N.7°E., 31.5 ft. (Rec. N.7°E., 32.0 ft.) 1967
10" now 11" dia. tipped out to north, down and burnt cedar, scribing visible "¼ S BT" bears S.75°E., 27.0 ft. to remnants of roots, (agrees with record, first noted in 1974 Ren) source unknown.
12" now 18" dia. cedar with a partially healed single blaze, scribing visible "¼ S3 BT" bears N.89½°W., 124.9 ft (Rec. N.88½°W., 122.6 ft) 1974 Northeast cedar BT from 1974 Ren. is gone.
14" now broken, shattered, rotted remains of indeterminable size near record bearing (N.70°E., 21.8 ft.) Possible orig. BT. cont. next pg

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 3

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Set - Plumbed position of 1973 DCS0 BC/IP is referenced, Iron pipe measured 36" long. The stamping "RESET 1989" is added to brass cap. BC/IP is returned to referenced position and now protrudes 6" above ground.

New BTs- 7" dia. D.Fir double blazed and scribed "¼ S3 CS BT" bears S.7½°W., 35.9 ft.
7" dia. madrone bark scribed "¼ S2 CS BT" bears S.59½°E., 67.4 ft.
4" dia. D.Fir double blazed and scribed "X BT" bears North, 43.1'

Corner lies along southwest edge of a dirt road.

Ron Quimby - Crew: N. Fromdahl & R. Olsen - 4/2015 - C.S.
File 65/87-44

Condition report only

Found - DCS0 brass cap
10" D.Fir N. 43.1 ft. good scar.
24"x5' tall stump N.7°E., 31.5, spike in center.
12" Madrone S.59°e., 67.4 ft. good scar.
16" D.Fir S.7°W., 35.9 ft. good scar.
24" cedar N.89°W., 124.9 ft. good scar.

Note - Hand held GPS Lat & Long
N 42°59.354
W 123°44.507
Corner is on edge of old skid road.