

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION 1, 2, 11, & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, US Deputy Surveyor under contract 57 dated April 12, 1855 - (DCSO Records Vol. 17 Page(s) 7388  
-----  
Set post, cor. secs. 1, 2, 11, & 12, from which  
A fir, 36" dia., bears N.5°E. 20 lks.  
A fir, 15" dia., bears S.25°W. 44 lks.  
A fir, 10" dia., bears N.85°W. 21 lks.  
A cedar, 12" dia., bears S.20°E. 10 lks.

Douglas Co. Surveyors Office - James W. Byron, Deputy - M. Godfrey & S. Bilow - July 17, 18, 1958 - C.S. File 49/100-7  
-----  
Found - Hub with tack at corner.  
Dead Cedar, now 14" dia S.25°W. 6.6 ft. This has been chopped open & scribing "30S R9W 2" visible. Chopped out lower scar & found face had rotted before growing over. Tree has grown so slowly that rings are too fine to count.  
W.Fir Snag, now 25" diam. N.85°W. 13.9 ft. Bark Scribing "T30 R9W S2" visible. Portions of letters widely separated showing considerable growth since being scribed.  
Rotted Remnants of Large Fir Stump N.5°E. 13.2 ft. Stump Hole to S.W. which fits bearing & for old BT in Sec. 11.  
Set Brass Cap at corner Mkd S 2 | S 1 T30S R9W County Surveyors  
S11 | S12 Office, 1958.  
New BTs- 14" D.Fir S.88½°W., 23.1 ft. scribed "T30S R9W S11 CS BT"  
11" I.cedar S.66°E. 32.5 ft. scribed "T30S R9W S12 CS BT".  
44" D.Fir N.85°E. 18 ft. scribed "T30S R9W S1 CS BT".  
5" I.Cedar N.14°W. 31.5 ft. scribed "S2 CS BT".

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Mike Darby - July 27-31, 1964 - C.S. File 53/53-51  
-----  
Found - Brass cap & IP in good condition. 1958  
All orig. BTs completely destroyed by fire, renewal BTs mkd. in 1958, dead & scribe burned off all except,  
44" D.Fir N.85°E. 18.0 ft & 5" cedar N.14°W. 31.5 ft  
New BTs- 9" Cedar N.37½°W., 184.7 ft. mkd: T30S R9W S2 CS BT.  
Note - This Corner lies on SW slope approx. 100.0 ft. above small creek.  

Cont.

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION 1, 2, 11, & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

FD. OK 1/12/1974 - B. Shaner - M49-51
Howard Johnstone - For: Rsbg Lumber Co - Nov. 1988 - M101-44 ----- CORNER REPORT ONLY Found - 1958 County BCIP marked 2, 1, 12, 11 6" cedar, N.14°W., 31.5 ft. now down. 16" cedar, N.37½°W., 184.7 ft. healed. 46" fir, N.85°E. 18.0 ft. Now stump, scribe visible. 12" cedar, S.66°E., 32.5 ft. Dead.
Tony Hostetter - For: Roseburg Resources Co. Co. - May/July 2003 - M142-69 ----- Found - 1958 DCS0 brass cap 46" DF stump w/vis. scribes bears N.86°E. 18.0' 23" Cedar w/healed face bears N.37½°W., 184.7' 9" Pine w/visible scribes bears N.80¾°E., 7.0' 5" DF with visible scribes bears S.36¼°E. 29.5' 11" DF with visible scribes bears S.32°W., 8.5' 11" Pine w/visible scribes bears N.14¼°W. 15.0'
FD. Ok by T. Hostetter, 1/2007 - M152-28
BLM Dependent resurvey by A. Bert Skeesick Cadastral Surveyor, under Group No. 1973 surveyed March 2001 - (DCS0 records Vol. 54 Page(s) 20795-6) ----- The cor. of secs. 1, 2, 11, and 12, perpetuated by Byron, in 1958, from original evidence no longer in existence, further perpetuated by Tracy, in 1964, and recovered by Johnstone, in 1988; monumented with an iron post, 1½" dia., firmly set, projecting 18" above ground, with brass cap (properly) mkd. from which the remains of bearing trees mkd. by Byron A sawed and decayed stump, 46" dia., bears N.86½°E., 18.0 ft., with scribe marks T30S R9W S1 CS BT visible. A cedar snag, 16" dia., bears S.67¼°E., 32.5 ft., no marks visible. and bearing tree mkd. by Tracy A cedar, 23" dia., bears N.37½°W., 184.7 ft., with a healed blaze. and new bearing trees A pine, 9" dia. bears N.80¾°E. 7.0 ft. mkd. T30S R9W S1 BT A fir, 4" dia., bears S.36¼°E., 29.5 ft., mkd. X BT. A fir, 11" dia. bears S.32°W. 8.5 ft. mkd. T30S R9W S11 BT A pine, 11" dia., bears N.14¼°W., 15.0 ft., mkd. T30S R9W S2 BT.