

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, US Deputy Surveyor under contract 57 dated April 12, 1855 - (DCSO Records Vol. 17 Page(s) 7389

Set ¼ sec. post, from which
 A fir, 6" dia., bears N.30°W. 5 lks.
 A fir, 5" dia., bears S.15°E. 4 lks.

Howard Johnstone - For: Rsbj Lumber Co. - Nov 1988 - M101-44

Set - 5/8"x36" iron rod and alum. cap mkd: "¼ S1/S12"
 24" fir, S.13°E., 19.8 ft. "¼ S12 BT"
 12" fir, N.2°E., 13.4 ft. "¼ S1 BT"

BLM Dependent resurvey by A Bert Skeesick Cadastral Surveyor, under Group No. 1973 surveyed May 2001 - (DCSO recs Vol. 54 Pg 20795)

Point for the ¼ sec. cor. of secs. 1 and 12 at proportionate dist.; there is no remaining evidence of the original corner. Set a stainless steel post, 28" long, 2½" dia., 23" in the ground, with brass cap mkd. T 30 S R 9 W

¼
 S 1
 S 12
 2001 from which

A fir, 18" dia., bears S.4°E., 24.1 ft., mkd. ¼ S12 BT.
 A fir, 14" dia., bears N.63½°W., 30.8 ft., mkd. ¼ S1 BT.
 Deposit a magnet in a white plastic case at the base of the stainless steel post.
 From this point, a point established as the ¼ sec cor of secs 1 & 12, by Howard Johnstone, in 1988, bears N.63°57'05"E., 74.45 ft., monumented with a rebar, 5/8" dia., firmly set projecting 19" above the ground, with aluminum cap marked, T30S RR R9W ¼ S1 S12 1988 LS498. This cor. was not correctly positioned and is not used in the course of this survey.

Tony Hostetter - For: Roseburg Resources Co. - May/July 2003 - M142-69

Found - 2002 BLM Brass cap
 16" DF with visible scribes - bears N.63½°W., 30.8'
 19" DF with visible scribes - bears S.4°W., 24.1'

Scribed- "¼ SS BT" on 8" GF - bears N.1°W., 3.0 ft.
 "¼ S12 BT" on 10" DF - bears S.53°E., 26.9 ft.

Note - Per narrative - Some corners established on M101-44 were set incorrect. The N¼ S12 monument was pulled per Roseburg Resources request.